



PAVEMENT MANAGEMENT SYSTEM

PAVEMENT ASSESSMENT (PHASE 1)



Client: **Langeberg**

28/10/2015

Routine Maintenance

Langeberg

Assessment Date : 2011/05

Suburb	Street :	Segment From	To	Route Class	Existing Surfacing	Attention Required			Patching Surfacing	Edge Struc	Crack Break	Seal
						Rehab	Reseal	Action				
Main Arterials	Kerk	Johan de Jongh	Toets Sentrum	P	Cape			Rehab (H)				**
Main Arterials	Kerk	Toets Sentrum	Toets Sentrum	P	Cape			Rehab (H)				**
Main Arterials	Kerk	Toets Sentrum	Industria	P	Cape				*****	***		**
Main Arterials	Kerk	Industria	Denne	P	Cape	REHAB	????	Rehab (H)	***	**	***	**
Main Arterials	Kerk	Denne	Lang	P	C Slurry		****	Rehab (H)	*			**
Main Arterials	Kerk	Lang	Dirkie Uys	P	C Slurry		****	Rehab (H)			***	**
Main Arterials	Kerk	Dirkie Uys	Reitz	P	C Slurry		****	Rehab (H)				**
Main Arterials	Kerk	Reitz	Paul Kruger	P	C Slurry		****	Rehab (H)				**
Main Arterials	Muskadel	Cinnaut	Barlinka	S	13.2+6.7			Mod 13.2		**	***	**
Main Arterials	Muskadel	Barlinka	Road 2	S	13.2+6.7	REHAB	????	Rehab (M)	****	**	*****	*****
Main Arterials	Muskadel	Road 2	Siprus	S	13.2+6.7			Rehab (M)		***	*****	***
Main Arterials	Muskadel	Siprus	Road 1	S	13.2+6.7	REHAB	????	Rehab (M)	***	***	***	*****
Main Arterials	Muskadel	Road 1	Eike	S	13.2+6.7	REHAB	????	Rehab (M)	**	***	***	***
Main Arterials	Van Riebeeck	Van Huysteen	Klipna Circle	P	F Slurry			Asphalt (AC)				**
Main Arterials	Van Riebeeck	Klipna Circle	Exssen	P	F Slurry		***	Mod 13.2	**			*
Main Arterials	Van Riebeeck	Exssen	Kohler	P	F Slurry		****	Mod 13.2	**	*		**
Main Arterials	Van Riebeeck	Kohler	Kerk	P	F Slurry		****	Mod 13.2	**	*		**
Main Arterials	Van Riebeeck	Kerk	Swanepoel	P	13.2+6.7			Rehab (M)				**
Main Arterials	Van Riebeeck	Swanepoel	Brink	P	13.2+6.7	REHAB	????	Rehab (M)	***	***		**
Main Arterials	Van Riebeeck	Brink	Reitz	P	13.2+6.7		****	Slurry (CS)	***	*		**
Main Arterials	Van Riebeeck	Reitz	Prov Road (Start)	P	13.2+6.7		****	Mod 13.2	***			**
Ashbury	Akasia	Eike	Waboom	t	F Slurry			9.5mm	***			*
Ashbury	Akasia	Waboom	Alwyn	t	F Slurry			9.5mm	**	**		**
Ashbury	Akasia	Alwyn	Denne	t	F Slurry			9.5mm	*	***		*
Ashbury	Alwyn	Cul De Sac	Alwyn Link 2	t	F Slurry			9.5mm		**		**



PAVEMENT MANAGEMENT SYSTEM

PAVEMENT ASSESSMENT (PHASE 1)



Client: **Langeberg**

28/10/2015

Routine Maintenance

Langeberg

Assessment Date : 2011/05

Suburb	Street :	Segment		Route Class	Existing Surfacing	Attention Required			Patching		Edge Break	Crack Seal
		From	To			Rehab	Reseal	Action	Surfacing	Struc		
Ashbury	Alwyn	Alwyn Link 2	Silwerboom	t	F Slurry			9.5mm	***			
Ashbury	Bloekom	Mimosa	Mimosa	t	F Slurry			9.5mm	**	**		
Ashbury	Denne	Eike	Alwyn Link 2	t	F Slurry			9.5mm	**	**		**
Ashbury	Denne	Alwyn Link 2	Palm	t	F Slurry			Rehab (L)	***			**
Ashbury	Denne	Palm	Akasia	t	F Slurry			Mod 9.5				**
Ashbury	Eike	Muskadel	Mimosa	T	F Slurry		***	Rehab (M)	**	***		**
Ashbury	Eike	Mimosa	Jakaranda	T	F Slurry		****	Rehab (M)	***	**		**
Ashbury	Eike	Jakaranda	Denne	T	F Slurry		****	Rehab (M)	***	***		**
Ashbury	Eike	Denne	Silwerboom	T	F Slurry	REHAB	????	Rehab (M)	***	***		**
Ashbury	Eike	Silwerboom	Akasia	T	F Slurry			Mod 13.2	**	**		**
Ashbury	Eike	Akasia	Bloekom	T	F Slurry			Mod 13.2				**
Ashbury	Eike	Bloekom	Wilger	T	13.2+6.7		****	Slurry (CS)	***	**		**
Ashbury	Eike	Wilger	Rooikrans	T	13.2+6.7		****	Slurry (CS)	***	**		**
Ashbury	Jakaranda	Denne	Palm	t	F Slurry			Rehab (L)		**		***
Ashbury	Jakaranda	Palm	Eike	t	F Slurry			9.5mm	**	**		**
Ashbury	Karee	Salie	Olien	t	F Slurry				**	*		
Ashbury	Mimosa	Eike	Bloekom	t	F Slurry			9.5mm	**	***		**
Ashbury	Mimosa	Bloekom	Bloekom	t	F Slurry			9.5mm	**	**		
Ashbury	Palm	Gravel/Tar	Jakaranda	t	F Slurry			9.5mm		***		**
Ashbury	Palm	Jakaranda	Denne	t	F Slurry			9.5mm	*	**		**
Ashbury	Road 1	Muskadel	Road 3	t	13.2+6.7					**		
Ashbury	Road 1	Road 5	Road 4	t	13.2+6.7					***		
Ashbury	Road 4	Road 1	Road 3	t	13.2+6.7			Slurry (CS)	**	**		
Ashbury	Seder	Geelhout	Sitrus	t	13.2+6.7					***		**
Ashbury	Sipres	Muskadel	Sitrus	t	13.2+6.7		***	Rehab (L)	***	***	***	**
Ashbury	Sitrus	Sipres	Seder	t	13.2+6.7		***	Rehab (L)	**	***		**



PAVEMENT MANAGEMENT SYSTEM

PAVEMENT ASSESSMENT (PHASE 1)



Client: **Langeberg**

28/10/2015

Routine Maintenance

Langeberg

Assessment Date : 2011/05

Suburb	Street :	Segment From	To	Route Class	Existing Surfacing	Attention Required			Patching Surfacing	Edge Struc	Crack Break	Seal
						Rehab	Reseal	Action				
Ashbury	Sitrus	Seder	Geelhout	t	13.2+6.7			DE ??	***			
Ashbury	Sitrus	Geelhout	Ficus	t	13.2+6.7			DE ??	**	***		
Ashbury	Sitrus	Ficus	Doringboom	t	13.2+6.7			DE ??		***		
Ashbury	Sitrus	Doringboom	Hibiscus	t	13.2+6.7			DE ??		*****		
Ashbury	Waboom	Akasia	Waboom	t	13.2+6.7			DE ??		***	***	
Ashbury	Waboom	Waboom	Olyfboom	t	13.2+6.7			DE ??	**	**	***	
Ashbury	Waboom	Olyfboom	Waboom	t	13.2+6.7			DE ??		**		
Ashbury	Wilger	Eike	Populier	t	ASPH(C)		****	9.5mm	**	**		
Ashton	1st Ave	Grav (2nd Ave)	Abbatoir	t	9.5mm	REHAB	????	Rehab (L)	***	*****	***	**
Ashton	2nd Ave	Abbatoir	Tar/Gravel	t	9.5mm		***	FS + Mod9	*****	*****		**
Ashton	Abbatoir	Industria	1st Ave	T	9.5mm		****	Slurry (FS)	**	*	***	*
Ashton	Abbatoir	1st Ave	2nd Ave	T	9.5mm		***	DE ??	***	**	***	**
Ashton	Abbatoir	2nd Ave	3rd Ave	T	13.2+6.7		****	Slurry (CS)	***	*****	***	**
Ashton	Abbatoir	3rd Ave	CDS (Tar/Gravel)	t	13.2+6.7		****	Rehab (L)	****	***	***	***
Ashton	Industria	Abbatoir	Tar/Gravel	t	9.5mm			DE ??	*	**		**
Badshoogte	Angelier	Cul De Sac	Protea	t	13.2+6.7			DE ??		**		
Badshoogte	Angelier	Protea	Ranonkel	t	13.2+6.7			DE ??	***			*
Badshoogte	Angelier	Ranonkel	Aster	t	13.2+6.7			DE ??	***			*
Badshoogte	Angelier	Aster	Prov Road	t	13.2+6.7			DE ??	*			**
Badshoogte	Aster	Cul De Sac	Angelier	t	13.2+6.7			DE ??	***			
Badshoogte	Aster	Dahlia	Protea	t	13.2+6.7			Slurry (FS)	***	**		**
Badshoogte	Badskop Cres	Castle	Castle	t	C Slurry		****	Rehab (L)	****	***		**
Badshoogte	Castle	Muller	Badskop Cres	t	C Slurry			9.5mm	***	**		**
Badshoogte	Castle	Badskop Cres	Badskop Cres	t	13.2+6.7			DE ??	***	***		**
Badshoogte	Castle	Badskop Cres	Wessels	t	13.2+6.7		***	Slurry (FS)	***	***		**



PAVEMENT MANAGEMENT SYSTEM

PAVEMENT ASSESSMENT (PHASE 1)



Client: **Langeberg**

28/10/2015

Routine Maintenance

Langeberg

Assessment Date : 2011/05

Suburb	Street :	Segment From To	Route Class	Existing Surfacing	Attention Required			Patching Surfacing	Edge Struc	Crack Break	Seal
					Rehab	Reseal	Action				
Badshoogte	Dahlia	Protea	Aster	t	13.2+6.7		Slurry (FS)	***	*		**
Badshoogte	Fouche	Uitvlucht	Wessels	t	C Slurry		Slurry (CS)		*		**
Badshoogte	Magnolia	Protea	Cul De Sac	t	13.2+6.7		Slurry (FS)	**	***		**
Badshoogte	Muller	Prov Road	Castle	T	C Slurry	***	13.2mm	***	***		**
Badshoogte	Protea	Prov Road	Aster	T	13.2+6.7		Rehab (L)		**		***
Badshoogte	Protea	Aster	Dahlia	T	13.2+6.7	****	Rehab (L)	***	***		**
Badshoogte	Protea	Dahlia	Ranonkel	t	13.2+6.7		DE ??	***			**
Badshoogte	Protea	Vygie	Angelier	t	13.2+6.7		DE ??	***	**		
Badshoogte	Ranonkel	Protea	Angelier	t	13.2+6.7		Slurry (FS)	***			**
Badshoogte	Ranonkel	Angelier	Cul De Sac	t	13.2+6.7		DE ??		*		**
Badshoogte	Truter	Wessels	Cul De Sac	t	C Slurry	***	9.5mm	***	**		**
Badshoogte	Uitvlucht	Prov Road	Wessels	T	F Slurry	****	Rehab (M)	***	**		**
Badshoogte	Uitvlucht	Wessels	Burger	T	F Slurry		Rehab (HS)				**
Badshoogte	Uitvlucht	Burger	Fouche	T	F Slurry		Rehab (HS)		***		**
Badshoogte	Uitvlucht	Fouche	Wessels	T	F Slurry		Rehab (L)		**		**
Badshoogte	Uitvlucht	Wessels	CDS (Gate)	T	F Slurry		Rehab (HS)	**	***		**
Badshoogte	Vygie	Protea	Cul De Sac	t	13.2+6.7		DE ??		***		
Badshoogte	Wessels	Uitvlucht	Phillips	t	9.5mm		DE ??	***			**
Badshoogte	Wessels	Fouche	Burger	t	9.5mm	***	Slurry (FS)	***	*		**
Badshoogte	Wessels	Burger	Castle	t	C Slurry	***	9.5mm	**	**		**
Badshoogte	Wessels	Castle	Uitvlucht	t	C Slurry		9.5mm	*	**		**
Bonnievale	Akasia	Kruin	Karee	t	Sand	****	Slurry (FS)	*	**		
Bonnievale	Akasia	Karee	Olien	t	Sand		Rehab (L)	**	***		**
Bonnievale	Akasia	Olien	Kruin 2	t	9.5mm		Mod 9.5		**		
Bonnievale	Almeria	Buitekant	Lombard	T	13.2+6.7		Slurry (FS)		**		



PAVEMENT MANAGEMENT SYSTEM

PAVEMENT ASSESSMENT (PHASE 1)



Client: **Langeberg**

28/10/2015

Routine Maintenance

Langeberg

Assessment Date : 2011/05

Suburb	Street :	Segment From	To	Route Class	Existing Surfacing	Attention Required			Patching Surfacing	Edge Struc	Crack Break	Seal
Bonnievale	Almeria	Lombard	New Cross	T	13.2+6.7		***	Slurry (FS)	**			
Bonnievale	Almeria	Milners	Braaf	t	F Slurry			Slurry (CS)	**	*****		
Bonnievale	Almeria	Braaf	Almeria CDS	t	C Slurry			9.5mm			***	**
Bonnievale	Almeria	Almeria CDS	Rock	t	9.5mm			DE ??	***		****	**
Bonnievale	Barlinka Close	Barlinka	Tar/Gravel	t	9.5mm			DE ??		***	****	
Bonnievale	Bester	Reitz	Main	t	F Slurry		****	Rehab (M)	****	***		**
Bonnievale	Braaf	Cul De Sac	Almeria	t	13.2mm	REHAB	????	Rehab (L)		*****	***	
Bonnievale	Braaf	Almeria	Milners	t	9.5mm			Slurry (FS)	**	***	***	
Bonnievale	Buite Cres 1	Kruin 2	Kruin 1	t	C Slurry					***		*
Bonnievale	Buite Cres 2	Kruin 2	Buite Cres Close	t	9.5mm			Slurry (FS)	**	**		*
Bonnievale	Buite Cres Close	Buite Cres 2	Cul De Sac	t	13.2+6.7			DE ??	***	***		
Bonnievale	Buitekant	Almeria	Moos Snyman	t	13.2+6.7			DE ??		**	**	
Bonnievale	Buitekant	Moos Snyman	Moos Snyman	t	13.2+6.7			DE ??		***	**	
Bonnievale	Buitekant	Moos Snyman	New Cross	t	13.2+6.7			Slurry (FS)		***		
Bonnievale	Coetzee	Main	Van Zyl	t	6.7mm			DE ??	****			
Bonnievale	Forrest	Gravel/Tar + 2300m	Kruin	t	6.7mm			Slurry (CS)		***	**	
Bonnievale	Forrest	Myrtle Rigg	Reitz	T	6.7mm		***	Slurry (CS)	**	**		*
Bonnievale	Forrest	Reitz	Waterkant	T	6.7mm			Slurry (CS)		***		
Bonnievale	Forrest	Waterkant	Kort	T	6.7mm			Mill+Replace				*
Bonnievale	Forrest	Kort	Middel	T	6.7mm		***	Slurry (CS)	**			**
Bonnievale	Forrest	Middel	Keerom	T	6.7mm			Mill+Replace	**			
Bonnievale	Forrest	Keerom	Van Zyl	T	6.7mm			Slurry (CS)	**			*
Bonnievale	Forrest	Van Zyl	Main	T	6.7mm		****	Rehab (H)	***			**
Bonnievale	Forrest Link	Forrest	Waterkant	t	9.5mm			Slurry (FS)		***	***	
Bonnievale	Hanepoort	Hanepoort Close 1	Hanepoort Close 2	t	Sand			Mill+Replace				**
Bonnievale	Hanepoort	Hanepoort Close 2	Kristal	t	9.5mm		****	Slurry (FS)	***	**		



PAVEMENT MANAGEMENT SYSTEM

PAVEMENT ASSESSMENT (PHASE 1)



Client: **Langeberg**

28/10/2015

Routine Maintenance

Langeberg

Assessment Date : 2011/05

Suburb	Street :	Segment		Route Class	Existing Surfacing	Attention Required			Patching		Edge Break	Crack Seal
		From	To			Rehab	Reseal	Action	Surfacing	Struc		
Bonnievale	Hanepoort	Kristal	Hanepoort Close 3	t	9.5mm			DE ??	***	***		
Bonnievale	Hanepoort	Hanepoort Close 3	Cul De Sac	t	9.5mm		****	Slurry (FS)	***	*****		
Bonnievale	Hanepoort Close 2	Hanepoort	Cul De Sac	t	Sand			Mill+Replace	***	***		*
Bonnievale	Hill	CDS North	Hill A	t	Sand					**	**	*
Bonnievale	Hill	Hill A	Kloof	t	Sand					***		**
Bonnievale	Hill A	CDS West	Hill	t	Sand			Mod 9.5		***		**
Bonnievale	Hoop	Cul De Sac	Voortrekker	t	6.7mm		****	Mill+Replace	****	***	**	
Bonnievale	Hoop	Voortrekker	Cul De Sac	t	6.7mm			Mill+Replace	***	***	**	**
Bonnievale	Karee	Akasia	Akasia	t	Sand			Mod 9.5	**	***		*
Bonnievale	Keerom	Forrest	Cul De Sac	t	6.7mm			Slurry (CS)		*****		
Bonnievale	Kelkiewyn	Protea	Road 8	T	6.7mm			Mill+Replace	**	**	***	
Bonnievale	Kelkiewyn	Road 8	Aarbeiboom	T	6.7mm			Mill+Replace	***	**	**	
Bonnievale	Kerk	Hoop	Rigg	S	6.7mm		****	CS + Mod13	**			**
Bonnievale	Kerk	Van der Merwe	Van Zyl	S	6.7mm			Slurry (CS)		**		**
Bonnievale	Kerk	Van Zyl	Main	S	6.7mm		****	Slurry (CS)	****			**
Bonnievale	Keurboom	Protea	Protea	T	6.7mm			Rehab (L)	**	***		
Bonnievale	Keurboom	Protea	Leeubekkie	T	6.7mm			DE ??		**		
Bonnievale	Keurboom	Leeubekkie	Vygie	T	6.7mm		***	DE ??	***	**		
Bonnievale	Keurboom	Vygie	Buitekant	T	6.7mm			DE ??	**	**		
Bonnievale	Kloof	Cul De Sac	Hill	t	C Slurry			Mod 9.5	**	**	****	*
Bonnievale	Kloof	Hill	Rock	t	C Slurry			Mod 9.5		**	***	**
Bonnievale	Kort	Forrest	Cul De Sac	t	6.7mm			DE ??	**	***		
Bonnievale	Kruin	Kruin 2	Akasia	t	9.5mm					**		*
Bonnievale	Kruin	Akasia	Voortrekker	t	6.7mm		****	Slurry (FS)	***			**
Bonnievale	Kruin 1	Kruin 2	Buite Cres 1	t	9.5mm			Mod 9.5		**		**
Bonnievale	Kruin 1	Buite Cres 1	Kruin	t	9.5mm			9.5mm				**



PAVEMENT MANAGEMENT SYSTEM

PAVEMENT ASSESSMENT (PHASE 1)



Client: **Langeberg**

28/10/2015

Routine Maintenance

Langeberg

Assessment Date : 2011/05

Suburb	Street :	Segment From	To	Route Class	Existing Surfacing	Attention Required			Patching Surfacing	Edge Struc	Crack Break	Seal
Bonnievale	Kruin 2	Kruin 4	Kruin 1	t	9.5mm			Mod 9.5				**
Bonnievale	Kruin 2	Kruin 1	Kruin	t	9.5mm			Mod 9.5	**	**		**
Bonnievale	Kruin 2	Olien	Buite Cres 2	t	9.5mm			DE ??		**		*
Bonnievale	Kruin 2	Buite Cres 2	Akasia	t	9.5mm		****	Slurry (CS)	***	***		**
Bonnievale	Kruin 4	Buite Cres 1	Forrest	t	9.5mm			DE ??	**	**		**
Bonnievale	Landbou	Gravel/Tar	Main	T	6.7mm	REHAB	????	Rehab (HS)	**	**	***	*
Bonnievale	Leeubekkie	Bloekom	Bloekom	t	6.7mm			DE ??	**	*		
Bonnievale	Leeubekkie	Bloekom	Roos	t	6.7mm			DE ??	**	**		
Bonnievale	Leeubekkie	Roos	Aarbeiboom	t	13.2+6.7			DE ??	***	***		
Bonnievale	Leeubekkie	Landbou	Road 6	t	13.2+6.7			DE ??	**	**		
Bonnievale	Leeubekkie	Road 6	Silwerboom	t	13.2+6.7			DE ??	***	***		
Bonnievale	Lombard	Almeria	Pietersen	t	C Slurry			9.5mm		**	***	
Bonnievale	Louisiana	Cul De Sac	Louisiana Close	t	6.7mm					***		*
Bonnievale	Louisiana	Louisiana Close	Main	t	6.7mm					*****		**
Bonnievale	Madeliefie	Almeria	Madeliefie Slot 1	t	C Slurry					**		
Bonnievale	Malherbe	Waterkant	Main	t	6.7mm	REHAB	????	Rehab (L)	****	***	***	**
Bonnievale	Middel	Forrest	Cul De Sac	t	6.7mm			Slurry (CS)				
Bonnievale	Milners	Almeria	Frans	T	9.5mm		***	Slurry (CS)	***	**		
Bonnievale	Milners	Frans	Adendorf	T	9.5mm			Slurry (CS)	**	**		
Bonnievale	Milners	Hanepoort	Barlinka	T	9.5mm		***	Mill+Replace	***			**
Bonnievale	Milners	Barlinka	Kristal	T	9.5mm			DE ??	**	**		
Bonnievale	Milners	Sultana	Hanepoort	T	9.5mm		***	Mill+Replace	***	**		
Bonnievale	Moos Snyman	Pietersen	Buitekant	t	F Slurry				***	**	***	*
Bonnievale	Muller	Cul De Sac	Van der Merwe	t	13.2+6.7		****	Slurry (CS)	***	**		*
Bonnievale	Muller	Kerk	Kerk	S	13.2+6.7		****	Asphalt (AC)	***	**		**
Bonnievale	Muller	Kerk	Cul De Sac	t	13.2+6.7			Slurry (CS)		***		**



PAVEMENT MANAGEMENT SYSTEM

PAVEMENT ASSESSMENT (PHASE 1)



Client: **Langeberg**

28/10/2015

Routine Maintenance

Langeberg

Assessment Date : 2011/05

Suburb	Street :	Segment From	To	Route Class	Existing Surfacing	Attention Required			Patching Surfacing	Edge Struc	Crack Break	Seal
						Rehab	Reseal	Action				
Bonnievale	Myrtle Rigg	Myrtle Rigg Close	CDS West	t	6.7mm				**	**		
Bonnievale	Myrtle Rigg Close	Myrtle Rigg	Cul De Sac	t	6.7mm			Mod 9.5	**	***		**
Bonnievale	New Cross	Madeliefie	New Cross Close 1	T	F Slurry					**	**	
Bonnievale	New Cross	New Cross Close 2	Frans	t	F Slurry					**		
Bonnievale	New Cross	Frans	Sultana	t	9.5mm			DE ??				*
Bonnievale	New Cross Close 2	New Cross	Tar/Gravel	t	9.5mm			DE ??		***		
Bonnievale	Olien	Akasia	Kruin Cres 2	t	Sand					**		*
Bonnievale	Pietersen	Moos Snyman	Lombard	t	6.7mm			DE ??		***		*
Bonnievale	Protea	Kelkiewyn	Roos	T	6.7mm					**	***	**
Bonnievale	Protea	Roos	Besembos	T	C Slurry					**		
Bonnievale	Protea	Besembos	Roos.	T	6.7mm				**	**		
Bonnievale	Reitz	Forrest	Bester	t	6.7mm			Mill+Replace		***	***	**
Bonnievale	Rigg	CDS 1	Kerk	t	6.7mm			Mill+Replace		***		
Bonnievale	Rigg	Kerk	CDS 2	t	6.7mm		****	DE ??	***	**		**
Bonnievale	Road 6	Leeubekkie	Road 7	t	13.2+6.7				***	***		
Bonnievale	Road 6	Road 7	Landbou	t	13.2+6.7					****		
Bonnievale	Roos	Protea	Protea	t	6.7mm	REHAB	????	Rehab (L)	***	***	**	
Bonnievale	Roos	Protea	Protea.	t	6.7mm		***	Rehab (L)	***	***	**	
Bonnievale	Roos	Protea.	Leeubekkie	t	6.7mm			Slurry (FS)	***	***		
Bonnievale	Silwerboom	Main	Leeubekkie	t	C Slurry			Rehab (L)	***	*****		***
Bonnievale	Silwerboom	Leeubekkie	Silwerboom Close	t	6.7mm		***	Slurry (FS)	***	**		
Bonnievale	Silwerboom	Silwerboom Close	Gousblom	t	6.7mm			Mill+Replace		***		**
Bonnievale	Silwerboom	Gousblom	Kelkiewyn	t	6.7mm		***	Slurry (FS)	***	**	***	
Bonnievale	Sultana	Sultana Close	Milners	t	9.5mm			FS + Mod9	**			**
Bonnievale	Tuin	Waterkant	Tuin Close	t	9.5mm			Slurry (FS)	**	***		**
Bonnievale	Tuin	Tuin Close	Cul De Sac	t	9.5mm			DE ??		**		



PAVEMENT MANAGEMENT SYSTEM

PAVEMENT ASSESSMENT (PHASE 1)



Client: **Langeberg**

28/10/2015

Routine Maintenance

Langeberg

Assessment Date : 2011/05

Suburb	Street :	Segment From	To	Route Class	Existing Surfacing	Attention Required			Patching Surfacing	Edge Struc	Crack Break	Seal
Bonnievale	Tuin Close	Tuin	Cul De Sac	t	9.5mm				***			*
Bonnievale	Uitsig	Louisiana	Cul De Sac	t	6.7mm	REHAB	????	Rehab (M)	*****			
Bonnievale	Van Zyl	Cul De Sac	Kerk	t	6.7mm		***	Slurry (CS)	***	**		
Bonnievale	Van Zyl	Kerk	Coetzee	t	6.7mm		***	Slurry (FS)	**	***		
Bonnievale	Van Zyl	Coetzee	Forrest	t	6.7mm		****	DE ??	***			**
Bonnievale	Van der Merwe	Cul De Sac	Kerk	S	13.2+6.7		****	FS + Mod13	***	***		
Bonnievale	Van der Merwe	Kerk	Kerk	S	13.2+6.7			Slurry (CS)				**
Bonnievale	Violtjie Cres	Botterboom	Kelkiewyn	t	13.2+6.7				***	****		
Bonnievale	Wade	New Cross	New Cross	t	F Slurry			Mod 9.5	**	***	**	*
Bonnievale	Waterkant	Forrest	Tuin	t	6.7mm		***	DE ??	***	*	**	
Bonnievale	Waterkant	Tuin	Kerk	t	6.7mm			Slurry (CS)	***	**		**
Bonnievale	Waterkant	Kerk	Malherbe	t	Sand			Rehab (L)		**	***	**
Bonnievale	Waterkant	Malherbe	Cul De Sac	t	Sand	REHAB	????	Rehab (L)	***	**	***	**
Cogmanskloof	Amirilla	Middel	Iris	t	9.5mm		***	DE ??	***	***		**
Cogmanskloof	Amirilla	Iris	Rose	t	9.5mm		***	DE ??	***	***		
Cogmanskloof	Amirilla	Rose	Jasmein	t	9.5mm			DE ??		***		
Cogmanskloof	Amirilla	Jasmein	Petunia	t	9.5mm			DE ??	**	***		
Cogmanskloof	Amirilla	Petunia	Lelie	t	9.5mm		****	FS + Mod9	****	**		**
Cogmanskloof	Aster	Blue Bell	Cul De Sac	t	13.2mm			DE ??	**	***		
Cogmanskloof	Begonia	Anemoon	Kiepersol	t	13.2+6.7					***		
Cogmanskloof	Bloekom	Denne	Gardenia	t	9.5mm		***	DE ??	***	***		**
Cogmanskloof	Blue Bell	Iris	Madeliefie	t	13.2mm		***	DE ??	***	***		
Cogmanskloof	Blue Bell	Madeliefie	Narsing	t	13.2mm		****	Slurry (FS)	*****	**		
Cogmanskloof	Blue Bell	Aster	Jasmein	t	13.2mm			DE ??		**		
Cogmanskloof	Coronation	Lelie	Krisant	t	9.5mm		***	DE ??	***	*****		**



PAVEMENT MANAGEMENT SYSTEM

PAVEMENT ASSESSMENT (PHASE 1)



Client: **Langeberg**

28/10/2015

Routine Maintenance

Langeberg

Assessment Date : 2011/05

Suburb	Street :	Segment		Route Class	Existing Surfacing	Attention Required			Patching		Edge	Crack
		From	To			Rehab	Reseal	Action	Surfacing	Struc	Break	Seal
Cogmanskloof	Coronation	Krisant	Jasmein	t	9.5mm			Rehab (L)		*****		
Cogmanskloof	Coronation	Jasmein	Iris	t	9.5mm	REHAB	????	Rehab (L)	***	*****		
Cogmanskloof	Coronation	Iris	Middel	t	13.2+6.7		***	DE ??	***	***		
Cogmanskloof	Coronation	Middel	Protea	t	9.5mm			DE ??	**	**		
Cogmanskloof	Coronation	Marula	Jakaranda	t	9.5mm			DE ??	**	***		
Cogmanskloof	Coronation	Karee	Wilger	t	9.5mm			DE ??		***		**
Cogmanskloof	Coronation	Wilger	Uitspan	t	9.5mm			DE ??		***		
Cogmanskloof	Delphinium	Iris	Krisant	t	9.5mm	REHAB	????	Rehab (L)	***	*****		*****
Cogmanskloof	Denne	Bloekom	Uitspan	t	9.5mm			DE ??	**	**		
Cogmanskloof	Disa	Jakaranda	Wilger	t	9.5mm			DE ??		***		
Cogmanskloof	Disa	Wilger	Uitspan	t	9.5mm			DE ??	**	***		
Cogmanskloof	Gardenia	Middel	Mahonie	t	9.5mm		****	Rehab (L)	***	*****		
Cogmanskloof	Gardenia	Mahonie	Sipres	t	9.5mm			DE ??				
Cogmanskloof	Gardenia	Sipres	Marula	t	9.5mm			DE ??			***	
Cogmanskloof	Gardenia	Marula	Bloekom	t	9.5mm		***	DE ??	*****		***	
Cogmanskloof	Gardenia	Bloekom	Karee	t	9.5mm		****	Slurry (FS)	***	***		
Cogmanskloof	Gardenia	Karee	Uitspan	t	9.5mm			DE ??	***	***		
Cogmanskloof	Gladioli	Krisant	Ranonkel	t	9.5mm		***	DE ??	***	***		*****
Cogmanskloof	Gladioli	Ranonkel	Iris	t	9.5mm			Rehab (L)	**	*****		
Cogmanskloof	Iris	Ranonkel	Gladioli	t	9.5mm		***	DE ??	***	*****		
Cogmanskloof	Iris	Gladioli	Delphinium	t	9.5mm		***	DE ??	***	*****		
Cogmanskloof	Iris	Delphinium	Coronation	t	9.5mm			DE ??	**			**
Cogmanskloof	Iris	Blue Bell	Amirilla	t	F Slurry				**	***		
Cogmanskloof	Jakaranda	Coronation	Disa	t	13.2+6.7				***	***		
Cogmanskloof	Jakaranda	Disa	Acacia	t	9.5mm		****	DE ??	*****	*****		**
Cogmanskloof	Jakaranda	Acacia	Main	t	13.2+6.7		***	DE ??	***	**		*****



PAVEMENT MANAGEMENT SYSTEM

PAVEMENT ASSESSMENT (PHASE 1)



Client: **Langeberg**

28/10/2015

Routine Maintenance

Langeberg

Assessment Date : 2011/05

Suburb	Street :	Segment From	To	Route Class	Existing Surfacing	Attention Required			Patching Surfacing	Edge Struc	Crack Break	Seal
Cogmanskloof	Jasmein	Amirilla	Blue Bell	t	13+Sand					***		
Cogmanskloof	Krisant	Coronation	Delphinium	t	9.5mm		****	Slurry (FS)	***	***		**
Cogmanskloof	Krisant	Delphinium	Gladioli	t	9.5mm			DE ??	**	***		
Cogmanskloof	La Rochelle	Zandvliet	Zandvliet	t	9.5mm		***	FS + Mod9	**	**		**
Cogmanskloof	Lelie	Cul De Sac	Orgidee	t	9.5mm		***	DE ??	***	***		
Cogmanskloof	Lelie	Orgidee	Amirilla	t	9.5mm		***	Slurry (FS)	**	***		
Cogmanskloof	Lelie	Amirilla	Coronation	t	9.5mm		****	Rehab (L)	***	***		**
Cogmanskloof	Madeliefie	Blue Bell	Cul De Sac	t	13.2mm			DE ??		***		
Cogmanskloof	Magnolia	Dahlia	Middel	t	F Slurry					***		
Cogmanskloof	Mahonie	Olien	Gardenia	t	F Slurry		****	9.5mm	**	*		
Cogmanskloof	Marula	Gardenia	Coronation	t	F Slurry			9.5mm	*	**		
Cogmanskloof	Middel	Main	Acacia	T	Cape	REHAB	????	Rehab (L)	***	***		****
Cogmanskloof	Middel	Acacia	Coronation	T	F Slurry		****	13.2mm	***	***		**
Cogmanskloof	Middel	Coronation	Gardenia	T	F Slurry		***	13.2mm	***	***		**
Cogmanskloof	Middel	Gardenia	Ranonkel	T	F Slurry		***	13.2mm	***	***		
Cogmanskloof	Noord	Bruwer	Voortrekker	t	9.5mm		***	Slurry (FS)	**	**		***
Cogmanskloof	Noord	Voortrekker	Uitspan	t	9.5mm			DE ??		**		
Cogmanskloof	Olien	Sipres	Bloekom	t	9.5mm			DE ??	*	*		
Cogmanskloof	Olien	Bloekom	Uitspan	t	9.5mm		***	Slurry (FS)	**	*****		
Cogmanskloof	Orgidee	Lelie	Cul De Sac	t	9.5mm		***	DE ??	***	*****		
Cogmanskloof	Petunia	Rose Cres	Amirilla	t	13.2+6.7		***	Rehab (L)	**	*****		
Cogmanskloof	Populier	Begonia	Bloekom	t	13+Sand					*****		
Cogmanskloof	Protea	Coronation	Acacia	t	F Slurry			9.5mm	**	***		
Cogmanskloof	Ranonkel	Gladioli	Iris	t	9.5mm		****	DE ??	*****	*****		
Cogmanskloof	Rose Cres	Petunia	Amirilla	t	9.5mm		****	Slurry (FS)	***	*****		**
Cogmanskloof	Sipres	Gardenia	Olien	t	F Slurry			9.5mm	**	***		



PAVEMENT MANAGEMENT SYSTEM

PAVEMENT ASSESSMENT (PHASE 1)



Client: **Langeberg**

28/10/2015

Routine Maintenance

Langeberg

Assessment Date : 2011/05

Suburb	Street :	Segment From To	Route Class	Existing Surfacing	Attention Required			Patching Surfacing	Edge Struc	Crack Break	Seal
Cogmanskloof	Uitspan	Olien Denne	t	9.5mm			DE ??	***			
Cogmanskloof	Uitspan	Gardenia Coronation	t	9.5mm			DE ??	**			
Cogmanskloof	Uitspan	Coronation Disa	t	9.5mm			DE ??	**	*		
Cogmanskloof	Uitspan	Disa Main	t	9.5mm			DE ??	*	**		**
Cogmanskloof	Voortrekker	Noord Waterkant	t	9.5mm		****	FS + Mod9				**
Cogmanskloof	Voortrekker	Waterkant Faure	t	F Slurry		***	FS + Mod9	***			**
Cogmanskloof	Voortrekker	Faure Main	t	F Slurry		****	9.5mm	**			**
Cogmanskloof	Waterkant	Voortrekker Bruwer	t	9.5mm			CS + Mod9				**
Cogmanskloof	Wilger	Coronation Disa	t	9.5mm			DE ??	**	*****		
Cogmanskloof	Wilger	Disa Main	t	9.5mm			DE ??	**			**
Conradie Dorp	Barry	Swart Faure	t	C Slurry		***	9.5mm	**	***		***
Conradie Dorp	Barry	Faure Main	t	6.7mm			Mod 9.5		**		**
Conradie Dorp	Bruwer	Zandvliet Main	T	ASPH(C)			13.2mm				**
Conradie Dorp	Bruwer	Main Faure	T	F Slurry		***	13.2mm				**
Conradie Dorp	Bruwer	Faure Swart	T	F Slurry			13.2mm				**
Conradie Dorp	Buitekant	Cul De Sac Robertson	t	9.5mm			DE ??		***		
Conradie Dorp	Buitekant	Robertson Kloof	t	C Slurry		***	9.5mm	***	**		**
Conradie Dorp	De Villiers	Hoog Fullard	t	F Slurry		****	9.5mm	***	***		**
Conradie Dorp	De Wet	Fullard Swart	t	F Slurry			9.5mm				**
Conradie Dorp	Faure	George Barry	t	F Slurry		****	Rehab (HS)	***	**		**
Conradie Dorp	Faure	Barry Green	t	F Slurry	REHAB	????	Rehab (L)	***	**		***
Conradie Dorp	Faure	Green Bruwer	t	F Slurry			9.5mm				**
Conradie Dorp	Faure	Bruwer Voortrekker	t	F Slurry		****	Rehab (L)	***	**		**
Conradie Dorp	Fullard	George Skool	t	F Slurry			9.5mm				**
Conradie Dorp	Fullard	Skool De Wet	t	F Slurry			9.5mm				**



PAVEMENT MANAGEMENT SYSTEM

PAVEMENT ASSESSMENT (PHASE 1)



Client: **Langeberg**

28/10/2015

Routine Maintenance

Langeberg

Assessment Date : 2011/05

Suburb	Street :	Segment		Route Class	Existing Surfacing	Attention Required			Patching		Edge	Crack
		From	To			Rehab	Reseal	Action	Surfacing	Struc	Break	Seal
Conradie Dorp	Fullard	De Wet	De Villiers	t	F Slurry			9.5mm				***
Conradie Dorp	George	Faure	Swart	T	F Slurry		****	13.2mm	**	*		**
Conradie Dorp	George	Swart	Fullard	T	F Slurry		****	Rehab (L)	***			**
Conradie Dorp	George	Fullard	Paul Kruger	T	F Slurry		****	Rehab (L)	***	*****		**
Conradie Dorp	George	Kloof	Robertson	T	C Slurry		****	Rehab (HS)	***	***		**
Conradie Dorp	George	Montagu	Cul De Sac	t	9.5mm			DE ??		***		
Conradie Dorp	Green	Cul De Sac	Park	t	13.2+6.7		****	Slurry (FS)	***	***		**
Conradie Dorp	Green	Park	Wium	t	13.2+6.7		****	Rehab (HS)	**	**		***
Conradie Dorp	Green	Hoog	Fullard	t	F Slurry			9.5mm				**
Conradie Dorp	Green	Fullard	Swart	t	F Slurry			9.5mm		**		**
Conradie Dorp	Green	Swart	Faure	t	F Slurry		****	9.5mm	***			**
Conradie Dorp	Hoog	De Villiers	Skool	t	F Slurry			9.5mm				**
Conradie Dorp	Kort	Wium	Cul De Sac	t	F Slurry			9.5mm	***	***	***	**
Conradie Dorp	Loop	Main	Cul De Sac	t	F Slurry			Mod 9.5		***	***	**
Conradie Dorp	Montagu	George	Paul Kruger	t	9.5mm			DE ??		***		**
Conradie Dorp	Montagu	Paul Kruger	Roodewal	t	9.5mm			Slurry (FS)				**
Conradie Dorp	Paul Kruger	George	Riviera	T	C Slurry		****	Rehab (HS)		***		**
Conradie Dorp	Paul Kruger	Riviera	Riviera	T	C Slurry			Rehab (HS)		***		**
Conradie Dorp	Paul Kruger	Riviera	Robertson	t	C Slurry		****	9.5mm	***			**
Conradie Dorp	Paul Kruger	Montagu	Tindale	t	C Slurry			Rehab (L)		**		***
Conradie Dorp	Paul Kruger	Tindale	Prov Gravel Road	t	C Slurry			9.5mm		*****		***
Conradie Dorp	Riviera	Paul Kruger	Paul Kruger	t	9.5mm		****	Rehab (HS)	***	**		**
Conradie Dorp	Robertson	Roodewal	Paul Kruger	t	F Slurry		***	9.5mm	**	**		**
Conradie Dorp	Robertson	Paul Kruger	George	T	F Slurry			13.2mm				**
Conradie Dorp	Robertson	George	Buitekant	t	9.5mm		****	DE ??	*****	***		
Conradie Dorp	Roodewal	Prov Gravel Road	Tindale	t	9.5mm		****	DE ??	***	***		



PAVEMENT MANAGEMENT SYSTEM

PAVEMENT ASSESSMENT (PHASE 1)



Client: Langeberg

28/10/2015

Routine Maintenance

Langeberg

Assessment Date : 2011/05

Suburb	Street :	Segment From To	Route Class	Existing Surfacing	Attention Required Rehab Reseal Action			Patching Surfacing	Edge Struc	Crack Break	Seal
Conradie Dorp	Roodewal	Tindale	Montagu	t	F Slurry		****	9.5mm	***	**	**
Conradie Dorp	Roodewal	Montagu	Robertson	t	F Slurry			9.5mm		***	**
Conradie Dorp	Skool	Hoog	Fullard	t	F Slurry			9.5mm		***	**
Conradie Dorp	Station	Prov Road	Tar/Gravel	t	9.5mm			DE ??	*****		**
Conradie Dorp	Swart	De Villiers	Barry	t	F Slurry			9.5mm	**		**
Conradie Dorp	Swart	Barry	De Wet	t	F Slurry			9.5mm	**		**
Conradie Dorp	Tindale	Roodewal	Paul Kruger	t	F Slurry			9.5mm	***		**
Conradie Dorp	Zandvliet	La Rochelle	La Rochelle	t	Cape			Mod 9.5	**	**	
Conradie Dorp	Zandvliet	La Rochelle	Spoorlyn (CDS)	t	Cape			Mod 9.5	**	**	***
Droeheuwel	Lusembos 1	Bloubos	Bloubos	t	F Slurry				***		
Droeheuwel	Rolbos	Bloekombos	Taaibos	t	Cape				**		
Droeheuwel	Rolbos	Bloubos	Doringbos	t	Cape				**		
Droeheuwel	Rolbos	Bloubos	Paddy	t	Cape				**		
McGregor	Barry	Mill	Voortrekker	t	Cape			Slurry (CS)	**	***	**
McGregor	Barry	Voortrekker	Long	t	Cape			Slurry (CS)	**	**	****
McGregor	Bree	Long	Voortrekker	t	Cape				*	*	*
McGregor	Buitekant	Barry	Loop	t	13.2+6.7			DE ??		**	
McGregor	Church	Gate (CDS)	Gewe	t	9.5mm			Slurry (CS)	**	**	*
McGregor	Church	Mill	Voortrekker	t	13.2+6.7			Slurry (CS)			**
McGregor	Church	Voortrekker	Long	t	13.2+6.7			Slurry (CS)	**	***	***
McGregor	Hartzenberg	Buitekant	Cul De Sac	t	13.2+6.7			Slurry (CS)	**	***	***
McGregor	Long	Lady Grey	Keerom	T	9.5mm				**	**	**
McGregor	Long	Tindall	Church	T	Cape				*	**	
McGregor	Long	Church	Bree	t	Cape					*	
McGregor	Loop	Buitekant	Long	t	13.2+6.7			DE ??		***	



PAVEMENT MANAGEMENT SYSTEM

PAVEMENT ASSESSMENT (PHASE 1)



Client: **Langeberg**

28/10/2015

Routine Maintenance

Langeberg

Assessment Date : 2011/05

Suburb	Street :	Segment		Route Class	Existing Surfacing	Attention Required			Patching		Edge	Crack
		From	To			Rehab	Reseal	Action	Surfacing	Struc	Break	Seal
McGregor	Loop	Long	Voortrekker	t	9.5mm			DE ??	**	**	***	
McGregor	Loop	Voortrekker	Mill	t	13.2+6.7			DE ??	**	**	***	
McGregor	Loop	Mill	Tar/Gravel	t	13.2+6.7			Slurry (FS)	***	***		
McGregor	McGregor 2	Long	Cul De Sac	t	Cape				**	***		
McGregor	Mill	Office	Loop	t	9.5mm			Slurry (CS)	***	***		*
McGregor	Office	Buitekant	McGregor 1	t	13.2+6.7			DE ??		**	***	
McGregor	Office	McGregor 1	Long	t	13.2+6.7			Slurry (CS)	**	***	***	**
McGregor	Office	Long	Voortrekker	t	13.2+6.7			Slurry (CS)	**	***	***	**
McGregor	Office	Voortrekker	Mill	t	9.5mm			DE ??	**	**	***	**
McGregor	Office	Mill	Cul De Sac	t	13.2+6.7			Slurry (FS)	**	***	***	**
McGregor	Piet October	Piet October	Piet October	t	Cape					***	***	
McGregor	Piet Visser	Willie Meyer	Buitekant	t	13.2+6.7			Slurry (CS)	***	***	***	*
McGregor	Plein	Long	Voortrekker	t	Cape					*		
McGregor	Smith	Darling	Mill	t	Cape				**	***	**	
McGregor	Smith	Mill	Voortrekker	t	Cape			Slurry (CS)	**	***		
McGregor	Tindall	Gewe	Mill	T	Cape				**	**	**	*
McGregor	Tindall	Mill	Voortrekker	T	Cape				**	**	***	*
McGregor	Tindall	Voortrekker	Long	T	Cape			Slurry (CS)		**		**
McGregor	Tindall	Long	Buitekant	T	Cape			Slurry (CS)		***		*
McGregor	Van Niekerk	Willie Meyer	Willie Meyer	t	13.2+6.7		***	Slurry (CS)	**	***		
McGregor	Voortrekker	Gravel (P 1334)	Smith	t	9.5mm		***	Slurry (FS)	**	***		
McGregor	Voortrekker	Smith	Plein	t	9.5mm				**	***		
McGregor	Voortrekker	Loop	Barry	t	9.5mm							
McGregor	Willie Meyer	Buitekant	Van Niekerk	t	13.2+6.7			Rehab (L)	**	***	**	**
McGregor	Willie Meyer	Van Niekerk	Van Niekerk	t	13.2+6.7			Slurry (CS)		***		*
McGregor	Willie Meyer	Van Niekerk	Piet Visser	t	13.2+6.7			FS + Mod9	**	***		**



PAVEMENT MANAGEMENT SYSTEM

PAVEMENT ASSESSMENT (PHASE 1)



Client: **Langeberg**

28/10/2015

Routine Maintenance

Langeberg

Assessment Date : 2011/05

Suburb	Street :	Segment		Route Class	Existing Surfacing	Attention Required			Patching		Edge	Crack
		From	To			Rehab	Reseal	Action	Surfacing	Struc	Break	Seal
Montagu	Africa	Wilhelm Thys	Andries	t	9.5mm			Slurry (FS)	**	**		
Montagu	Amandel	Keerom	Loop	t	13.2+6.7		***	Slurry (FS)	***	**		**
Montagu	Amandel	Loop	Cul De Sac	t	13.2+6.7		***	DE ??	****	***		**
Montagu	Anderson	Du Preez	Van Wyk	t	9.5mm			Slurry (FS)	**	*		
Montagu	Anderson	Van Wyk	Du Preez	t	9.5mm			DE ??	**	**		
Montagu	Andries	Banie	Johnson	t	9.5mm			DE ??				*
Montagu	Andries	Johnson	Africa	t	9.5mm			DE ??		*		
Montagu	Banie	Wilhelm Thys	Goetham	t	F Slurry			9.5mm	**	*		
Montagu	Banie	Goetham	Andries	t	F Slurry		****	9.5mm	**	*		
Montagu	Banie	Fluks	Buitekant	t	F Slurry			9.5mm		***		**
Montagu	Barry	Cul De Sac	Meul	t	13.2+6.7		****	Slurry (FS)	***	***		
Montagu	Barry	Meul	Bell	T	F Slurry		***	Mod 13.2	**	**		**
Montagu	Barry	Bell	Bath	T	F Slurry		****	Mod 13.2	**			**
Montagu	Barry	Bath	Lang	T	6.7mm				**	**		**
Montagu	Bath	Rose	Barry	T	C Slurry		****	Rehab (L)	***	**		***
Montagu	Bell	Barry	Cul De Sac	t	13.2+6.7		***	DE ??	***	***		
Montagu	Bloem	Kruin Cres	Le Roux	t	F Slurry			9.5mm	***	**		*
Montagu	Bloem	Le Roux	Joubert	t	F Slurry			9.5mm		**		*
Montagu	Bloem	Joubert	Piet Retief	t	F Slurry			Mod 9.5	**	**		**
Montagu	Bloem SB	Piet Retief	Bath	T	F Slurry			Slurry (CS)	***	***		**
Montagu	Bloupunt	Swanepoel	Cogmans Close	t	13.2+6.7			DE ??	**	*		**
Montagu	Bloupunt	Cogmans Close	Cul De Sac	t	13.2+6.7			DE ??	**	**		
Montagu	Boesak	Fluks	Goetham	t	13.2+6.7			DE ??	**	**		
Montagu	Bree	Linvelt	Grave	t	13.2+6.7		***	DE ??	***	**		**
Montagu	Brink	Cul De Sac	Van der Merwe	t	6.7mm			DE ??		***		



PAVEMENT MANAGEMENT SYSTEM

PAVEMENT ASSESSMENT (PHASE 1)



Client: **Langeberg**

28/10/2015

Routine Maintenance

Langeberg

Assessment Date : 2011/05

Suburb	Street :	Segment		Route Class	Existing Surfacing	Attention Required			Patching		Edge	Crack
		From	To			Rehab	Reseal	Action	Surfacing	Struc	Break	Seal
Montagu	Brink	Van der Merwe	Hofmeyer	t	6.7mm		****	Slurry (FS)	***			*
Montagu	Brink	Hofmeyer	Van Riebeeck	t	6.7mm			Slurry (FS)	***	**		**
Montagu	Brown	Rose	Middel	T	13.2+6.7			DE ??	*	***	***	
Montagu	Buitekant	Prov Road	Ismael	T	9.5mm		***	Slurry (FS)	**	***		**
Montagu	Buitekant	Montagu 3	Banie	T	9.5mm			DE ??	**	*		**
Montagu	Buitekant	Banie	Mark	T	9.5mm			FS + Mod13		*		**
Montagu	Buitekant	Mark	Du Toit	T	9.5mm			Rehab (L)		***		**
Montagu	Buitekant	Du Toit	Nel	t	F Slurry			FS + Mod9		**		**
Montagu	Cogmans Close	Bloupunt	Montagu 1	t	13.2+6.7		***	DE ??	***	****		**
Montagu	Cogmans Close	Montagu 1	Cul De Sac	t	13.2+6.7			DE ??	**	**		
Montagu	Cross	Le Roux	Joubert	t	F Slurry			Mod 9.5	**			**
Montagu	Cross	Joubert	Piet Retief	t	F Slurry			Mod 9.5	**			**
Montagu	Cross	Piet Retief	Bath	t	F Slurry			Mod 9.5	**	**		**
Montagu	Cross	Bath	Lang	T	F Slurry			Slurry (CS)	**	*		***
Montagu	Cupido	Wilhelm Thys	Van Turha	t	9.5mm			DE ??	**	**		
Montagu	Cupido	Van Turha	Mohammed	t	9.5mm			DE ??		*		
Montagu	Cupido	Mohammed	Stuart	t	9.5mm			Slurry (CS)	***			**
Montagu	Cupido	Stuart	Du Preez	t	9.5mm			Slurry (CS)	*	**		
Montagu	De Kock	Hofmeyer	Hospital	t	6.7mm		***	Slurry (FS)	***	**		**
Montagu	Diener	Knipes Hope	Polisie Stasie	t	13.2+6.7			9.5mm	**	***		*
Montagu	Du Preez	Cupido	Anderson	t	9.5mm			DE ??	*	**		
Montagu	Du Preez	Anderson	Felix	t	9.5mm			Slurry (FS)	**			
Montagu	Du Preez	Felix	Sacca	t	9.5mm		***	Slurry (FS)	***	**		
Montagu	Du Preez	Sacca	Cul De Sac	t	13.2+6.7		****	Slurry (FS)	***	**		
Montagu	Du Toit	Lang	Bath	T	F Slurry		****	Rehab (M)	***	***		**
Montagu	Du Toit	Bath	Piet Retief	T	F Slurry			Mod 13.2		**		**



PAVEMENT MANAGEMENT SYSTEM

PAVEMENT ASSESSMENT (PHASE 1)



Client: **Langeberg**

28/10/2015

Routine Maintenance

Langeberg

Assessment Date : 2011/05

Suburb	Street :	Segment		Route Class	Existing Surfacing	Attention Required			Patching		Edge	Crack
		From	To			Rehab	Reseal	Action	Surfacing	Struc	Break	Seal
Montagu	Du Toit	Piet Retief	Joubert	T	F Slurry			Mod 13.2				**
Montagu	Du Toit	Joubert	Le Roux	T	F Slurry			Mod 13.2		*		**
Montagu	Du Toit	Le Roux	Union	T	F Slurry			Mod 13.2				**
Montagu	Du Toit	Union	Buitekant	T	F Slurry			13.2mm		**		**
Montagu	Du Toit	Buitekant	Wilhelm Thys	T	13.2+6.7		***	Rehab (L)	**	**		**
Montagu	Ebden	Prov Road	Cul De Sac	t	9.5mm		****	Slurry (FS)	***	***		
Montagu	Eyssen	Hospital	Rossouw	t	6.7mm			Slurry (FS)	*	**		**
Montagu	Eyssen	Rossouw	Thomson	t	6.7mm			Slurry (FS)	*			**
Montagu	Eyssen	Van Riebeeck	Lang	t	6.7mm			Rehab (L)		**		**
Montagu	Felix	Wilhelm Thys	Pokwas	t	9.5mm			DE ??	***	**		
Montagu	Felix	Pokwas	Du Preez	t	9.5mm			DE ??	*	***		
Montagu	Fluks	Banie	Lekay	t	13.2+6.7			DE ??	**	**		
Montagu	Fluks	Lekay	Boesak	t	13.2+6.7			DE ??		***		
Montagu	Fluks	Boesak	Cul De Sac	t	13.2+6.7			DE ??		**		
Montagu	Goetham	Januarie	Ismael	t	9.5mm			DE ??		**		
Montagu	Goetham	Ismael	Titus	t	9.5mm			DE ??		**		
Montagu	Goetham	Titus	Lekay	t	9.5mm			DE ??		**		*
Montagu	Goetham	Lekay	Banie	t	9.5mm			DE ??		**		*
Montagu	Grave	Mount	Tanner	t	9.5mm			DE ??				**
Montagu	Grave	Tanner	Keerom	t	9.5mm			Slurry (FS)	***			**
Montagu	Grave	Keerom	Bree	t	9.5mm		***	Slurry (FS)	***			**
Montagu	Grave	Bree	Loop	t	9.5mm			Slurry (FS)	***			**
Montagu	Grave	Loop	Krom	t	9.5mm			DE ??	**			**
Montagu	Grave	Krom	Kort	t	9.5mm			Slurry (FS)				**
Montagu	Hof	Joubert	Piet Retief	t	13.2+6.7			Slurry (FS)	***	**		**
Montagu	Hofmeyer	Cul De Sac	Kerk	t	6.7mm			DE ??	**	*****		**



PAVEMENT MANAGEMENT SYSTEM

PAVEMENT ASSESSMENT (PHASE 1)



Client: **Langeberg**

28/10/2015

Routine Maintenance

Langeberg

Assessment Date : 2011/05

Suburb	Street :	Segment		Route Class	Existing Surfacing	Attention Required			Patching		Edge	Crack
		From	To			Rehab	Reseal	Action	Surfacing	Struc	Break	Seal
Montagu	Hofmeyer	Kerk	De Kock	t	6.7mm			DE ??	*	***		**
Montagu	Hofmeyer	De Kock	Swanepoel	t	6.7mm			Slurry (FS)	***			**
Montagu	Hofmeyer	Swanepoel	Brink	t	6.7mm			Slurry (FS)		**		**
Montagu	Hoog	Barry	Cul De Sac	t	13.2+6.7			Slurry (CS)	*	**		
Montagu	Hospital	Van Huysteen	Exssen	t	6.7mm			DE ??	***	*		*
Montagu	Hospital	Gravel/Tar	Kerk	t	6.7mm			Slurry (FS)	*	**		**
Montagu	Hospital	Kerk	De Kock	T	6.7mm		***	Slurry (FS)	***	**		**
Montagu	Hospital	De Kock	Swanepoel	T	6.7mm			Slurry (FS)	**	**		**
Montagu	Hospital	Swanepoel	Cul De Sac	t	6.7mm		***	DE ??	***	***		**
Montagu	Ismael	Buitekant	Pekeur	t	9.5mm			DE ??	**	**		
Montagu	Ismael	Pekeur	Saunders	t	9.5mm			DE ??		*		
Montagu	Ismael	Saunders	Goetham	t	9.5mm			DE ??	***	**		
Montagu	Ismael	Goetham	Wilhelm Thys	t	9.5mm		***	Slurry (FS)	***	**		
Montagu	Ismael	Wilhelm Thys	Simon	t	9.5mm			DE ??	**	*		
Montagu	Januarie	Goetham	Saunders	t	9.5mm			DE ??	**	**		
Montagu	Johnson	Andries	Wilhelm Thys	t	13.2+6.7			Slurry (FS)	**	***		
Montagu	Joubert	Rawson	Bloem	t	F Slurry			9.5mm	**	*		*
Montagu	Joubert	Bloem	Kohler	t	F Slurry			Mod 9.5	**	**		**
Montagu	Joubert	Kohler	Plein	t	F Slurry			Mod 9.5	**	**		**
Montagu	Joubert	Plein	Du Toit	t	F Slurry			Mod 9.5	*	**		**
Montagu	Joubert	Hof	Mark	t	F Slurry			Mod 9.5				**
Montagu	Joubert	Mark	Cross	t	F Slurry			Mod 9.5				**
Montagu	Keerom	Grave	Linvelt	t	13.2+6.7		***	FS + Mod9	***			**
Montagu	Keerom	Linvelt	Amandel	t	13.2+6.7		***	Slurry (FS)	***			**
Montagu	Keerom	Amandel	Cul De Sac	t	13.2+6.7		***	Slurry (FS)	***	****		**
Montagu	Kerk	Cul De Sac	Hospital	t	6.7mm			Rehab (HS)	*	*****		**



PAVEMENT MANAGEMENT SYSTEM

PAVEMENT ASSESSMENT (PHASE 1)



Client: **Langeberg**

28/10/2015

Routine Maintenance

Langeberg

Assessment Date : 2011/05

Suburb	Street :	Segment From	To	Route Class	Existing Surfacing	Attention Required			Patching Surfacing	Edge Struc	Crack Break	Seal
						Rehab	Reseal	Action				
Montagu	Kerk	Hospital	Hofmeyer	T	6.7mm			Rehab (HS)				**
Montagu	Kerk	Hofmeyer	Van Riebeeck	T	6.7mm		***	Slurry (CS)	**	***		**
Montagu	Kerk	Van Riebeeck	Lang	T	6.7mm	REHAB	????	Rehab (H)	***	**		*****
Montagu	Kerk	Lang	Bath	T	F Slurry			Mod 13.2		***		**
Montagu	Klassen	Ismael	Visser	t	13.2+6.7		****	Slurry (FS)	**	**		
Montagu	Klassen	Visser	Stevens	t	13.2+6.7		****	Slurry (FS)	****	***		
Montagu	Klipna Circle	Van Riebeeck	Cul De Sac	t	6.7mm			DE ??	**	***		**
Montagu	Kloof	Mount	Tar/Gravel	t	9.5mm			DE ??		***		
Montagu	Knipes Hope	Bath	Diener	t	C Slurry					*		
Montagu	Knipes Hope	Diener	Cul De Sac	t	13.2+6.7		***	Slurry (FS)	**	**		*
Montagu	Kohler	Gate (CDS)	Buitekant	t	13.2+6.7		***	Rehab (HS)	**	***		
Montagu	Kohler	Unie	Le Roux	t	F Slurry		****	9.5mm	**			**
Montagu	Kohler	Le Roux	Joubert	t	F Slurry		****	9.5mm	**			
Montagu	Kohler	Joubert	Piet Retief	t	F Slurry			9.5mm	***			*
Montagu	Kohler	Piet Retief	Bath	t	F Slurry			9.5mm				**
Montagu	Kohler	Bath	Lang	t	F Slurry		****	Rehab (M)	***			**
Montagu	Kohler	Lang	Cul De Sac	t	F Slurry			FS + Mod9	***	***		**
Montagu	Kohler	Cul De Sac	Van Riebeeck	t	6.7mm	REHAB	????	Rehab (L)	*****	*****		**
Montagu	Kohler	Van Riebeeck	CDS (Brug)	t	6.7mm			Rehab (L)		***		**
Montagu	Kort	Cul De Sac	Grave	t	13.2+6.7		***	Slurry (FS)	****			
Montagu	Kort	Grave	Klip	t	13.2+6.7			Slurry (FS)	***			**
Montagu	Kort	Klip	Linvelt	t	13.2+6.7			DE ??	**	*		**
Montagu	Krom	Grave	Kiesie	t	9.5mm		***	Slurry (FS)	***			**
Montagu	Krom	Kiesie	Grave	t	9.5mm		***	Slurry (FS)	***	**		**
Montagu	Kruin Cres	Bloem	Kohler	t	F Slurry			9.5mm	**	***		*
Montagu	Le Roux	Cross	Mark	t	F Slurry			Mod 9.5	**			**



PAVEMENT MANAGEMENT SYSTEM

PAVEMENT ASSESSMENT (PHASE 1)



Client: **Langeberg**

28/10/2015

Routine Maintenance

Langeberg

Assessment Date : 2011/05

Suburb	Street :	Segment		Route Class	Existing Surfacing	Attention Required			Patching		Edge	Crack
		From	To			Rehab	Reseal	Action	Surfacing	Struc	Break	Seal
Montagu	Le Roux	Mark	Du Toit	t	F Slurry			9.5mm	*	**		**
Montagu	Le Roux	Du Toit	Kohler	t	F Slurry			9.5mm	**			**
Montagu	Le Roux	Kohler	Bloem	t	F Slurry			9.5mm	***	**		**
Montagu	Lekay	Goetham	Fluks	t	13.2+6.7			Slurry (FS)	*	***		
Montagu	Linvelt	Cul De Sac	Kort	t	13.2+6.7		****	Slurry (FS)	***	**		
Montagu	Linvelt	Kort	Loop	t	13.2+6.7		***	Slurry (FS)	***			*
Montagu	Linvelt	Loop	Bree	t	13.2+6.7		***	DE ??	***	**		*
Montagu	Linvelt	Bree	Keerom	t	13.2+6.7		***	Slurry (FS)	***			**
Montagu	Loop	Cul De Sac	Amandel	t	13.2+6.7			DE ??		*		
Montagu	Loop	Amandel	Linvelt	t	13.2+6.7			DE ??	**	*		**
Montagu	Loop	Linvelt	Grave	t	13.2+6.7			DE ??				**
Montagu	Low	Prov Road	Tar/Gravel	t	F Slurry			Slurry (CS)	***	***	***	
Montagu	Mark	Lang	Bath	T	F Slurry	REHAB	????	Rehab (M)	*	***		***
Montagu	Mark	Bath	Piet Retief	T	F Slurry			Mod 13.2	*			**
Montagu	Mark	Piet Retief	Joubert	t	F Slurry			Mod 9.5				**
Montagu	Mark	Joubert	Le Roux	t	F Slurry			Mod 9.5	**	*		**
Montagu	Mark	Le Roux	Park	t	F Slurry			9.5mm				**
Montagu	Mark	Park	Union	t	F Slurry			Slurry (CS)				**
Montagu	Mark	Union	Buitekant	t	F Slurry			Mod 9.5				**
Montagu	Meul	Barry	Middel	t	9.5mm		****	Slurry (FS)	***			****
Montagu	Meul	Middel	Mount	t	9.5mm		***	Slurry (CS)	**	*		***
Montagu	Mohammed	Montagu 8	Cupido	t	9.5mm			DE ??		*		
Montagu	Montagu 3	Buitekant	Park	t	F Slurry			9.5mm	**	**		**
Montagu	Montagu 8	Stuart	Strydom	t	ASPH(C)			9.5mm	*	*		
Montagu	Montagu 8	Simon	Wilhelm Thys	t	ASPH(C)			9.5mm	**	**		*
Montagu	Mount	Meul	Grey	t	F Slurry		****	FS + Mod9	***			**



PAVEMENT MANAGEMENT SYSTEM

PAVEMENT ASSESSMENT (PHASE 1)



Client: **Langeberg**

28/10/2015

Routine Maintenance

Langeberg

Assessment Date : 2011/05

Suburb	Street :	Segment		Route Class	Existing Surfacing	Attention Required			Patching		Edge Break	Crack Seal
		From	To			Rehab	Reseal	Action	Surfacing	Struc		
Montagu	Mount	Grey	Mount Cl 1	t	F Slurry		***	Mod 9.5	***			**
Montagu	Mount	Mount Cl 1	Mount	t	F Slurry		****	FS + Mod9	****	***		**
Montagu	Mount	Mount	Kloof	t	F Slurry		***	Mod 9.5	***			**
Montagu	Mount Cl 1	Mount	Cul De Sac	t	F Slurry					****		
Montagu	Nel	Buitekant	Davids	t	13.2+6.7			Rehab (L)		***		**
Montagu	Park	Mark	Cross	t	F Slurry			9.5mm	**			**
Montagu	Park	Cross	Montagu 3	t	F Slurry			9.5mm		**		**
Montagu	Park	Montagu 3	Prov Road	t	F Slurry		***	9.5mm	***			**
Montagu	Parring	Andries	Wilhelm Thys	t	9.5mm			Slurry (FS)	***	***		
Montagu	Pekeur	Stevens	Ismael	t	9.5mm			Slurry (FS)	**	*		
Montagu	Piet Retief	Bath	Cross	t	F Slurry		***	Mod 9.5	***			**
Montagu	Piet Retief	Mark	Hof	t	F Slurry			Mod 9.5	**	**		**
Montagu	Piet Retief	Kohler	Bloem	t	F Slurry			Mod 9.5				***
Montagu	Piet Retief	Rawson	Barry	t	F Slurry		****	Mod 9.5	***	**		**
Montagu	Plein	Joubert	Piet Retief	t	13.2+6.7			Slurry (FS)	**	*		**
Montagu	Rawson	Piet Retief	Joubert	t	F Slurry			Mod 9.5				**
Montagu	Rawson	Joubert	Cul De Sac	t	6.7mm			Slurry (CS)	**	**		**
Montagu	Rose	Lang	Bath	t	F Slurry			9.5mm	***	**		**
Montagu	Rossouw	Van Huysteen	Van Zyl	t	6.7mm			DE ??	***	***		**
Montagu	Rossouw	Van Zyl	Exssen	t	6.7mm			DE ??	***	*		
Montagu	Saunders	Ismael	Januarie	t	13.2+6.7		****	Slurry (FS)	***	**		
Montagu	Saunders	Januarie	Stevens	t	13.2+6.7			Slurry (FS)	**	**		
Montagu	Simon	Montagu 8	Ismael	t	9.5mm		****	Slurry (FS)	***	***		
Montagu	Stevens	Klassens	Wilhelm Thys	t	13.2+6.7		***	FS + Mod9	**			**
Montagu	Stevens	Wilhelm Thys	Goetham	t	9.5mm			DE ??	*			
Montagu	Stevens	Goetham	Saunders	t	9.5mm			DE ??		**		



PAVEMENT MANAGEMENT SYSTEM

PAVEMENT ASSESSMENT (PHASE 1)



Client: Langeberg

28/10/2015

Routine Maintenance

Langeberg

Assessment Date : 2011/05

Suburb	Street :	Segment From	To	Route Class	Existing Surfacing	Attention Required			Patching		Edge	Crack
						Rehab	Reseal	Action	Surfacing	Struc	Break	Seal
Montagu	Stevens	Saunders	Pekeur	t	9.5mm			DE ??	**	*		
Montagu	Strydom	Ismael	Montagu 8	t	9.5mm		***	DE ??	***	**		**
Montagu	Stuart	Montagu 7	Montagu 8	t	9.5mm		***	Slurry (FS)	**	**		
Montagu	Sultana Cres (N)	Barlinka	Sultana Link	t	C Slurry		***	Rehab (L)	**	**		**
Montagu	Sultana Cres (S)	Sultana Link	Barlinka	t	C Slurry	REHAB	????	Rehab (L)	***	***		***
Montagu	Sultana Link	Prov Road	Sultana Cres	t	F Slurry			Slurry (CS)		**		***
Montagu	Swanepoel	Bloupunt	Hospital	t	13.2+6.7		****	Slurry (CS)	***	*		*
Montagu	Swanepoel	Van der Merwe	Hofmeyer	t	C Slurry			9.5mm	**	****		**
Montagu	Swanepoel	Hofmeyer	Van Riebeeck	t	C Slurry			9.5mm	***			**
Montagu	Tanner	CDS (Gate)	Kiesie	t	6.7mm			Slurry (FS)	**			**
Montagu	Tanner	Kiesie	Meul	t	13.2+6.7		***	Slurry (FS)	***			**
Montagu	Titus	Goetham	Wilhelm Thys	t	9.5mm			DE ??	**	**		
Montagu	Union	Kohler	Du Toit	t	F Slurry			Mod 9.5	*			**
Montagu	Union	Du Toit	Mark	t	F Slurry			9.5mm	*	**		**
Montagu	Van Huysteen	Thomson	Rossouw	t	6.7mm			Slurry (FS)	**	**		**
Montagu	Van Turha	Cupido	Montagu 8	t	9.5mm		***	DE ??	***	**		
Montagu	Van Wyk	Anderson	Van Wyk	t	13.2+6.7		****	Slurry (FS)	***	**		
Montagu	Van Wyk	Van Wyk	Van Wyk	t	13.2+6.7		****	Slurry (FS)	***	**		
Montagu	Van Zyl	Thomson	Rossouw	t	6.7mm			DE ??	*	**		**
Montagu	Van der Merwe	Swanepoel	Brink	t	6.7mm			Slurry (FS)	***	**		**
Montagu	Visser	Ismael	Klassen	t	13.2+6.7		****	Slurry (FS)	***	***		
Montagu	Wilhelm Thys	Montagu 5	Nel	t	13.2+6.7			Slurry (FS)	***	**		
Montagu	Wilhelm Thys	Nel	Du Toit	t	9.5mm			Slurry (FS)	*	**		
Montagu	Wilhelm Thys	Du Toit	Montagu 6	t	13.2+6.7			DE ??	***	**		
Montagu	Wilhelm Thys	Montagu 6	Parring	T	13.2+6.7			DE ??	*	*		
Montagu	Wilhelm Thys	Parring	Africa	t	13.2+6.7			DE ??	***	**		



PAVEMENT MANAGEMENT SYSTEM

PAVEMENT ASSESSMENT (PHASE 1)



Client: **Langeberg**

28/10/2015

Routine Maintenance

Langeberg

Assessment Date : 2011/05

Suburb	Street :	Segment From	To	Route Class	Existing Surfacing	Attention Required			Patching Surfacing	Edge Struc	Crack Break	Seal
						Rehab	Reseal	Action				
Montagu	Wilhelm Thys	Africa	Johnson	t	13.2+6.7			DE ??	***	*		
Montagu	Wilhelm Thys	Johnson	Banie	t	13.2+6.7			DE ??	**	*		
Montagu	Wilhelm Thys	Banie	Montagu 7	t	13.2+6.7			Slurry (FS)	**	*		
Montagu	Wilhelm Thys	Montagu 7	Titus	t	9.5mm		****	DE ??	*****			
Montagu	Wilhelm Thys	Titus	Montagu 8	t	ASPH(C)			Mod 9.5	**	*		
Montagu	Wilhelm Thys	Montagu 8	Ismael	t	ASPH(C)			Mod 9.5	**	**		**
Montagu	Wilhelm Thys	Ismael	Stevens	t	ASPH(C)			Rehab (M)	**	***		**
Montagu	Wilhelm Thys	Stevens	Prov Road	t	ASPH(C)	REHAB	????	Rehab (L)	***	**		*****
Montagu	Willem Lourens	Van Riebeeck	Cul De Sac	t	13.2+6.7			Slurry (FS)	**	**		*
Nkqubela	Burwana	Hani	Silimela	T	F Slurry			13.2mm		*		
Nkqubela	Burwana	May	Nokhonya	T	13.2+6.7			DE ??	**	**		
Nkqubela	Dayi	Samuel	Samuel	t	13.2+6.7			DE ??	*	***	*****	**
Nkqubela	Hani	Burwana	Silimela	t	13.2+6.7			Slurry (FS)	**	**		
Nkqubela	Luthuli	Nentsa	Cul De Sac	t	13.2+6.7			Slurry (FS)	***	**	***	
Nkqubela	Masakhane	Burwana	Hani	t	13.2+6.7			DE ??	**	**		**
Nkqubela	Mzola	Stuurman	Tar/Gravel	t	ASPH(C)		****	9.5mm	***	**	*****	
Nkqubela	Nentsa	Mzabalazo	Monyawaza	t	Cape					***		
Nkqubela	Peter	Nentsa	Qhanqiso	t	F Slurry			Rehab (L)		*****	***	
Nkqubela	Qhanqiso	May	Dantis	t	F Slurry			9.5mm	***	**	***	**
Nkqubela	Qhanqiso	Dantis	Peter	t	13.2+6.7			Slurry (FS)	**	*	***	
Nkqubela	Samuel	Silimela	Silimela	t	13.2+6.7		****	Slurry (FS)	***	*****		
Nkqubela	Samuel	Silimela	Dayi	t	13.2+6.7		****	Slurry (FS)	***	**		
Nkqubela	Silimela	Hani	Samuel	t	13.2+6.7		****	Slurry (FS)	***	***		
Nkqubela	Silimela	Samuel	Samuel	t	13.2+6.7		****	Slurry (FS)	***	***		
Nkqubela	Silimela	Samuel	Burwana	t	13.2+6.7		****	Slurry (FS)	***	***		



PAVEMENT MANAGEMENT SYSTEM

PAVEMENT ASSESSMENT (PHASE 1)



Client: **Langeberg**

28/10/2015

Routine Maintenance

Langeberg

Assessment Date : 2011/05

Suburb	Street :	Segment From	To	Route Class	Existing Surfacing	Attention Required			Patching Surfacing	Edge Struc	Crack Break	Seal
Nkqubela	Spoorn Serv	Burwana	Cul De Sac	t	13.2+6.7			DE ??	**	*****		
Nkqubela	Straat	Wolhunter	Cul De Sac	T	13.2+6.7		****	Rehab (L)	*****	**		
Nkqubela	Stuurman	Mzola	May	t	ASPH(C)			9.5mm		**		
Nkqubela	Tshazimpunzi	Hani	Cul De Sac	t	13.2+6.7		***	Slurry (FS)	***	**		
Nkqubela	Volt	Wolhunter	Cul De Sac	T	13.2+6.7	REHAB	****	Rehab (L)	**	*****		**
Nkqubela	Wolhunter	Prov Road	Straat	T	13.2+6.7	REHAB	****	Rehab (L)	**	**	*****	*****
Nkqubela	Wolhunter	Volt	Hani	T	13.2+6.7			DE ??		**	*****	
Robertson	Adderley	Kort	Dirkie Uys	T	6.7mm			Mod 13.2		*		**
Robertson	Adderley	Dirkie Uys	Dirkie Uys	T	6.7mm			13.2mm				**
Robertson	Adderley	Dirkie Uys	Reitz	T	F Slurry		****	Rehab (HS)	***	**		**
Robertson	Adderley	Reitz	Paul Kruger	t	F Slurry			Mod 9.5				**
Robertson	Adderley	Paul Kruger	Piet Retief	t	F Slurry			Mod 9.5		***		**
Robertson	Adderley	Piet Retief	Barry	t	F Slurry			9.5mm				**
Robertson	Adderley	Barry	Van der Stel	t	6.7mm		***	9.5mm	**			**
Robertson	Affodil	Nerina	Jasmyn	t	F Slurry			9.5mm	*	***		**
Robertson	Africa	Pietersen	Parking	t	13.2+6.7		***	Slurry (FS)	**	**		
Robertson	Africa Parking	Africa	Cul De Sac	t	9.5mm			DE ??		***		
Robertson	Akker	Eben Donges	Jakaranda	t	6.7mm			DE ??				**
Robertson	Akker	Jakaranda	Van Zyl	t	6.7mm		****	DE ??	*****	**		**
Robertson	Albert	Reitz	Paul Kruger	t	C Slurry			9.5mm	**	**		**
Robertson	Albert	Paul Kruger	Museum	t	C Slurry			9.5mm	*	*****		**
Robertson	Albert	Museum	Piet Retief	t	C Slurry			9.5mm				**
Robertson	Albert	Piet Retief	Barry	t	C Slurry			9.5mm				**
Robertson	Anthony	Solomon	Coetzee	t	13.2+6.7		****	Slurry (FS)	**	**		**
Robertson	Ash	Waterkant	Polack	t	C Slurry		****	Rehab (L)	***			**



PAVEMENT MANAGEMENT SYSTEM

PAVEMENT ASSESSMENT (PHASE 1)



Client: **Langeberg**

28/10/2015

Routine Maintenance

Langeberg

Assessment Date : 2011/05

Suburb	Street :	Segment		Route Class	Existing Surfacing	Attention Required			Patching		Edge Break	Crack Seal
		From	To			Rehab	Reseal	Action	Surfacing	Struc		
Robertson	Barry	Voortrekker (Paving)	Konstitusie	T	F Slurry		****	Rehab (H)	***	***		**
Robertson	Barry	Konstitusie	Victoria	T	F Slurry	REHAB	????	Rehab (H)	***	***		***
Robertson	Barry	Adderley	Hoop	T	6.7mm			Mod 13.2				**
Robertson	Barry	Swellendam	Mark	T	6.7mm			FS + Mod13				**
Robertson	Barry	Mark	Robertson	T	9.5mm			Rehab (H)				**
Robertson	Barry	Robertson	Van Reenen	T	6.7mm			Rehab (H)				**
Robertson	Barry	Van Reenen	White	T	6.7mm		****	Rehab (H)	**			**
Robertson	Barry	White	Truter	T	F Slurry			Rehab (H)				**
Robertson	Barry	Truter	Albert	T	F Slurry		****	13.2mm				**
Robertson	Barry	Albert	Le Roux	T	F Slurry			13.2mm	**			**
Robertson	Barry	Le Roux	Van Zyl	T	F Slurry			13.2mm				**
Robertson	Barry	Van Zyl	Loop	T	F Slurry		***	13.2mm		***		**
Robertson	Barry	Loop	Polack	T	F Slurry		***	13.2mm		***		**
Robertson	Bergsig	Paddy	Coligny	t	F Slurry			9.5mm		***		**
Robertson	Bergsig	Coligny	Erica	t	F Slurry			Mod 9.5				**
Robertson	Bergsig	Erica	Fleur	t	F Slurry			9.5mm		**		**
Robertson	Bergsig	Fleur	George	t	F Slurry			9.5mm				**
Robertson	Bergsig	George	Heuwel	t	F Slurry			9.5mm		***		**
Robertson	Bloekom	Jakaranda	Van Zyl	t	6.7mm		****	FS + Mod9	***	***		**
Robertson	Bosheuwel	Leeuwin	Waterkant	t	6.7mm			DE ??				**
Robertson	Buren	Drommedaris	Nassau	t	6.7mm			9.5mm	*	**		
Robertson	Buren	Nassau	Nassau	t	6.7mm			9.5mm		***		
Robertson	Ceder	Van Zyl	Jakaranda	t	9.5mm			DE ??	**	***		**
Robertson	Ceder	Eben Donges	Cul De Sac	t	9.5mm			Slurry (FS)	*	**		
Robertson	Clairvaux	CDS South	Willem Nel	t	13.2+6.7			Slurry (FS)	**	**		
Robertson	Clairvaux	Willem Nel	CDS North	t	13.2+6.7			DE ??	***	***		



PAVEMENT MANAGEMENT SYSTEM

PAVEMENT ASSESSMENT (PHASE 1)



Client: **Langeberg**

28/10/2015

Routine Maintenance

Langeberg

Assessment Date : 2011/05

Suburb	Street :	Segment		Route Class	Existing Surfacing	Attention Required			Patching		Edge Break	Crack Seal
		From	To			Rehab	Reseal	Action	Surfacing	Struc		
Robertson	Coetzee	Wesley	Johnson	t	9.5mm			DE ??	***			**
Robertson	Coetzee	Johnson	Tienvoet	t	9.5mm			DE ??		***		
Robertson	Coetzee	Unnamed Road 0007	Paul Kruger	T	9.5mm		****	Slurry (FS)				**
Robertson	Coligny	Bergsig	Dagbreek	t	6.7mm		***	9.5mm	***	*****		
Robertson	Constantia	Van der Stel	Cul De Sac	t	6.7mm			9.5mm	**	***		**
Robertson	Dagbreek	Paddy	Coligny	t	F Slurry		***	9.5mm	**	**		
Robertson	Dagbreek	Coligny	Erica	t	F Slurry		***	9.5mm	**	**		**
Robertson	Dagbreek	Erica	Heuwel	t	F Slurry		****	9.5mm	***	***		
Robertson	Dagbreek	Heuwel	Iris	t	13.2+6.7		****	DE ??	***	***		**
Robertson	Dahlia	Nutan	Jasmyn	t	F Slurry		****	9.5mm	*****	***		**
Robertson	De Villiers	Hospital	Hokim	t	Sand		***	Rehab (L)	**	*****		**
Robertson	De Wet	Unnamed Road 0007	Cul De Sac	t	13.2+6.7			DE ??		*****		
Robertson	Denne	Van Zyl	Elm	t	13.2+6.7			Slurry (FS)	**	*****		**
Robertson	Denne	Eben Donges	Kerk	t	13.2+6.7			Slurry (FS)	*			**
Robertson	Derde	Sonskyn	Vierde	t	F Slurry			9.5mm		***		
Robertson	Dirkie Uys	Van Zyl	Truter	T	F Slurry			Rehab (L)		**		**
Robertson	Dirkie Uys	Truter	Eben Donges	T	F Slurry		***	13.2mm		**		**
Robertson	Dirkie Uys	Eben Donges	Kerk	T	F Slurry		***	13.2mm	**	***		
Robertson	Dirkie Uys	Kerk	Hoop	T	6.7mm		***	13.2mm	**		***	**
Robertson	Dirkie Uys	Hoop	Adderley	T	6.7mm			Mod 13.2	*			**
Robertson	Dirkie Uys	Adderley	Konstitusie	t	6.7mm			Mod 9.5	*	**		**
Robertson	Dordrecht	Waterkant	Leeuwin	t	6.7mm			DE ??	**			**
Robertson	Dordrecht	Leeuwin	Parel	t	6.7mm		****	Slurry (FS)	*****	***		**
Robertson	Drommedaris	Buren	Van Zyl	t	13.2+6.7			FS + Mod9				**
Robertson	Eben Donges	Ceder	Akker	t	6.7mm			DE ??	**			**
Robertson	Eben Donges	Akker	Dirkie Uys	t	6.7mm			FS + Mod9				**



PAVEMENT MANAGEMENT SYSTEM

PAVEMENT ASSESSMENT (PHASE 1)



Client: **Langeberg**

28/10/2015

Routine Maintenance

Langeberg

Assessment Date : 2011/05

Suburb	Street :	Segment		Route Class	Existing Surfacing	Attention Required			Patching		Edge	Crack
		From	To			Rehab	Reseal	Action	Surfacing	Struc	Break	Seal
Robertson	Eerste	Derde	Tweede	t	13.2+6.7			Slurry (FS)	*****			
Robertson	Eerste	Tweede	Scholtz	t	13.2+6.7		****	Slurry (FS)	*****	***		
Robertson	Eerste	Hokim	Hager	t	F Slurry			9.5mm	***			**
Robertson	Elm	Van Zyl	Denne	t	6.7mm			Slurry (FS)	**	***		**
Robertson	Erica	Bergsig	Dagbreek	t	6.7mm		****	Slurry (FS)	***	***		**
Robertson	Ficus	Van Zyl	Cul De Sac	t	9.5mm		****	Rehab (M)	*****	***		**
Robertson	Fleur	Bergsig	Heuwel	t	6.7mm		****	Rehab (L)	***	*****		
Robertson	Freeman	White	Truter	t	6.7mm			DE ??	*	***		**
Robertson	Geelhout	Van Zyl	Cul De Sac	t	9.5mm		***	Slurry (FS)	**	***		
Robertson	George	Heuwel	Bergsig	t	ASPH(C)		***	Rehab (L)	**	***		**
Robertson	Gum Grove	Polack	Wavern	t	6.7mm			Slurry (FS)	*	***		**
Robertson	Hager	Eerste	Park	t	13.2+6.7			Slurry (FS)	*	**		**
Robertson	Hahn	Paddy	Cul De Sac	t	13.2+6.7		***	DE ??	***	***	*****	
Robertson	Heide	Vygie	Protea	t	6.7mm		****	Rehab (L)	***	*****		**
Robertson	Heide	Protea	Paddy	t	6.7mm		***	DE ??	***	***		**
Robertson	Heuwel	Dagbreek	Fleur	t	F Slurry			9.5mm		*****		**
Robertson	Heuwel	Fleur	Bergsig	t	9.5mm			9.5mm	*	*****		**
Robertson	Heuwel	Bergsig	Unnamed Road 0005	t	F Slurry			9.5mm	**	*****		**
Robertson	Heuwel	Unnamed Road 0005	George	t	F Slurry		***	9.5mm	***	*****		
Robertson	Heuwel	George	Unnamed Road 0006	t	F Slurry			Rehab (L)		*****		
Robertson	Hokim	River	De Villiers	t	C Slurry		****	9.5mm	**	***		**
Robertson	Hokim	De Villiers	Eerste	t	C Slurry			9.5mm		***		**
Robertson	Hoop	Dirkie Uys	Reitz	T	C Slurry		****	13.2mm	**			**
Robertson	Hoop	Reitz	Paul Kruger	T	F Slurry		***	13.2mm	**	***		**
Robertson	Hoop	Paul Kruger	Piet Retief	T	F Slurry			Rehab (L)		**		***
Robertson	Hoop	Piet Retief	Barry	T	F Slurry			13.2mm	*	*		***



PAVEMENT MANAGEMENT SYSTEM

PAVEMENT ASSESSMENT (PHASE 1)



Client: **Langeberg**

28/10/2015

Routine Maintenance

Langeberg

Assessment Date : 2011/05

Suburb	Street :	Segment		Route Class	Existing Surfacing	Attention Required			Patching		Edge	Crack
		From	To			Rehab	Reseal	Action	Surfacing	Struc	Break	Seal
Robertson	Hoop	Barry	Cul De Sac	t	C Slurry			9.5mm				**
Robertson	Hopley	Truter	Albert	t	6.7mm		****	9.5mm	*****	*****		**
Robertson	Hopley	Albert	Le Roux	t	F Slurry			CS + Mod9		***	***	**
Robertson	Hopley	Le Roux	Jeneke	t	F Slurry			9.5mm		**	***	**
Robertson	Hopley	Jeneke	Van Zyl	t	F Slurry			9.5mm		***	***	**
Robertson	Hopley	Van Zyl	Loop	t	F Slurry		***	9.5mm	***	***	*****	**
Robertson	Hospital	Eerste	Vygie	t	F Slurry			9.5mm		*		
Robertson	Hospital	Vygie	Protea	t	F Slurry			9.5mm				**
Robertson	Industria	Kerk	Voortrekker	t	9.5mm			Rehab (M)		***		**
Robertson	Iris	Unnamed Road 0006	Unnamed Road 0004	t	F Slurry		****	9.5mm	*****	***		**
Robertson	Iris	Unnamed Road 0004	Unnamed Road 0005	t	F Slurry			9.5mm	**	***		
Robertson	Jakaranda	Bloekom	Akker	t	6.7mm		***	DE ??		***		**
Robertson	Jansen	October	De Witt	t	13.2+6.7		***	Slurry (FS)	**	***		
Robertson	Jansen	De Witt	Pietersen	t	13.2+6.7			DE ??	**	***		**
Robertson	Japonika	Tulp	Watsonia	t	F Slurry			9.5mm				
Robertson	Jasmyn	Paddy	Saayman	t	F Slurry		***	9.5mm		*****		**
Robertson	Jasmyn	Saayman	Affodil	t	F Slurry			Mod 9.5				**
Robertson	Jasmyn	Affodil	Nutan	t	F Slurry			9.5mm	**			**
Robertson	Jasmyn	Nutan	Dahlia	t	F Slurry			9.5mm	**	***		
Robertson	Jasmyn	Watsonia	Sonneblom	t	F Slurry		***	9.5mm	***	***		**
Robertson	Jeneke	Hopley	Cul De Sac	t	13.2+6.7			DE ??		**		
Robertson	Johan de Jongh	Prov Road	Church	S	ASPH(C)			Mod 13.2				**
Robertson	Johan de Jongh	Church	Van Zyl	S	13.2+6.7			CS + Mod13			***	**
Robertson	Johan de Jongh	Van Zyl	Van Zyl + 500m	S	13.2+6.7			Slurry (CS)		**	***	**
Robertson	Johan de Jongh	Van Zyl + 500m	De Hoop	S	13.2+6.7			Rehab (M)		***		***
Robertson	Johan de Jongh	De Hoop	Van Oudtshoorn	S	13.2+6.7			Slurry (CS)	**	***	***	



PAVEMENT MANAGEMENT SYSTEM

PAVEMENT ASSESSMENT (PHASE 1)



Client: **Langeberg**

28/10/2015

Routine Maintenance

Langeberg

Assessment Date : 2011/05

Suburb	Street :	Segment		Route Class	Existing Surfacing	Attention Required			Patching		Edge Break	Crack Seal
		From	To			Rehab	Reseal	Action	Surfacing	Struc		
Robertson	Johan de Jongh	Van Oudtshoorn	Paul Kruger	T	13.2+6.7		***	Slurry (FS)	**		***	**
Robertson	Johnson	Coetzee	Solomon	t	13.2+6.7			DE ??		**		
Robertson	Johnson	Solomon	Cul De Sac	t	13.2+6.7			DE ??				**
Robertson	Jones	Nerina	Orley	t	13.2+6.7		****	Slurry (FS)	***	***		**
Robertson	Jubel	Muller	Unnamed Road 0004	t	6.7mm			DE ??	***	***		
Robertson	Jubel	Unnamed Road 0004	Unnamed Road 0003	t	6.7mm			DE ??		***		**
Robertson	Jubel	Unnamed Road 0003	Iris	t	6.7mm		****	Slurry (FS)	***	***		
Robertson	Keerom	Loop	Van Zyl	T	13.2+6.7							*
Robertson	Keerom	Van Zyl	Le Roux	T	13.2+6.7							*
Robertson	Keerom	White	Cul De Sac	t	13.2+6.7		***	Slurry (FS)	**	**		**
Robertson	King	Van Zyl	Cul De Sac	t	F Slurry			9.5mm		**		*
Robertson	Kloof	Langeberg	Unnamed Road 0003	t	F Slurry		***	9.5mm	**	*****		**
Robertson	Konstitusie	Voortrekker	Dirkie Uys	T	F Slurry	REHAB	????	Rehab (L)		*****		*****
Robertson	Konstitusie	Dirkie Uys	Reitz	T	ASPH(C)	REHAB	????	Rehab (L)	***	***		*****
Robertson	Konstitusie	Reitz	Paul Kruger	t	F Slurry		***	9.5mm	***	***		**
Robertson	Konstitusie	Paul Kruger	Piet Retief	t	F Slurry			Mod 9.5		***		**
Robertson	Konstitusie	Piet Retief	Barry	t	F Slurry			Mod 9.5				**
Robertson	Konstitusie	Barry	Cul De Sac	t	F Slurry			Mod 9.5		*****		**
Robertson	Kort	Adderley	Cul De Sac	t	ASPH(C)			9.5mm	**	***		
Robertson	Kromhout	Voortrekker	Polisie	t	F Slurry			Mod 9.5		***		**
Robertson	Kromhout	Polisie	Concrete (Private Rd)	t	F Slurry		***	9.5mm	***	***		**
Robertson	Lakey	Meyer	Cul De Sac	t	9.5mm			DE ??		*****		**
Robertson	Lang	Adderley	Kerk	t	6.7mm			Mod 9.5		*		**
Robertson	Langeberg	Paddy	Unnamed Road 0001	t	F Slurry			9.5mm	*			**
Robertson	Langeberg	Unnamed Road 0001	Heuwel	t	F Slurry		****	CS + Mod9	*			**
Robertson	Langeberg	Heuwel	Unnamed Road 0008	t	F Slurry		***	9.5mm	***	**		***



PAVEMENT MANAGEMENT SYSTEM

PAVEMENT ASSESSMENT (PHASE 1)



Client: Langeberg

28/10/2015

Routine Maintenance

Langeberg

Assessment Date : 2011/05

Suburb	Street :	Segment		Route Class	Existing Surfacing	Attention Required			Patching		Edge	Crack
		From	To			Rehab	Reseal	Action	Surfacing	Struc	Break	Seal
Robertson	Langeberg	Unnamed Road 0008	Kloof	t	ASPH(C)			9.5mm	**	***		**
Robertson	Langeberg	Kloof	Unnamed Road 0002	t	ASPH(C)		***	9.5mm	**			**
Robertson	Langeberg	Unnamed Road 0002	Kloof	t	ASPH(C)		***	9.5mm	**	***		**
Robertson	Le Roux	Hopley	Keerom	t	6.7mm			Mod 9.5	*	***		**
Robertson	Le Roux	Keerom	Barry	t	6.7mm		***	9.5mm				**
Robertson	Le Roux	Barry	Piet Retief	t	F Slurry			9.5mm		***		**
Robertson	Le Roux	Piet Retief	Paul Kruger	t	F Slurry			9.5mm				**
Robertson	Leeuwin	Cul De Sac	Bosheuwel	t	6.7mm		***	Rehab (L)	***	***		**
Robertson	Loop	Van Oudtshoorn	Paul Kruger	t	C Slurry			9.5mm				**
Robertson	Loop	Barry	Cul De Sac	t	6.7mm		****	Slurry (FS)	***	*****		***
Robertson	Loop	Cul De Sac	Keerom	t	6.7mm		****	Rehab (L)	***	*****		**
Robertson	Loop	Keerom	Hopley	t	F Slurry		***	Mod 9.5	**			**
Robertson	Malherbe	Van der Stel	Barry	t	C Slurry			Mod 9.5		***		**
Robertson	Malva	Unnamed Road 0002	Muller	t	ASPH(C)		***	9.5mm	***	***		
Robertson	Malva	Muller	Nerina	t	ASPH(C)		****	9.5mm	***	***		
Robertson	Malva	Nerina	Unnamed Road 0008	t	F Slurry			9.5mm		***		
Robertson	Malva	Unnamed Road 0008	Unnamed Road 0001	t	F Slurry		****	9.5mm	*****	***		
Robertson	Marais 2	Drommedaris	Marais 4	t	F Slurry			9.5mm		***		
Robertson	Meyer	Pietersen	Lakey	t	13.2+6.7			DE ??		**		**
Robertson	Muller	Malva	Malva	t	F Slurry			9.5mm		***		
Robertson	Muller	Malva	Langeberg	t	13.2+6.7		***	Slurry (FS)	**	***		
Robertson	Nerina	Paddy	Affodil	t	F Slurry		***	9.5mm	**	***		**
Robertson	Nerina	Affodil	Unnamed Road 0001	t	F Slurry			Mod 9.5				**
Robertson	Nerina	Unnamed Road 0001	Watsonia	t	F Slurry			Mod 9.5				**
Robertson	Nerina	Watsonia	Orley	t	F Slurry		****	Mod 9.5				**
Robertson	Nerina	Blocks/Tar	Jones	t	13.2+6.7		****	Slurry (FS)	*****			



PAVEMENT MANAGEMENT SYSTEM

PAVEMENT ASSESSMENT (PHASE 1)



Client: **Langeberg**

28/10/2015

Routine Maintenance

Langeberg

Assessment Date : 2011/05

Suburb	Street :	Segment		Route Class	Existing Surfacing	Attention Required			Patching		Edge	Crack
		From	To			Rehab	Reseal	Action	Surfacing	Struc	Break	Seal
Robertson	Nerina	Jones	Malva	t	Cape		***		***	***		**
Robertson	Nutan	Jasmyn	Dahlia	t	9.5mm		****	9.5mm	*****	***	***	**
Robertson	Nutan	Dahlia	Watsonia	t	F Slurry		****	9.5mm	**			**
Robertson	October	Jansen	Cul De Sac	t	6.7mm			Slurry (FS)	**	*****		
Robertson	Orley	Jones	Begonia	t	F Slurry			9.5mm	***	*****		
Robertson	Paddy	River	Heide	T	13.2+6.7			FS + Mod13	**			**
Robertson	Paddy	Heide	Bergsig	T	C Slurry		***	Mod 13.2	*	***		**
Robertson	Paddy	Bergsig	Vygie	T	C Slurry			Mod 13.2	*	**		**
Robertson	Paddy	Wesley	Langeberg	T	C Slurry			Mod 13.2		*		**
Robertson	Paddy	Nerina	Jasmyn	T	13.2+6.7			FS + Mod13	*	**		**
Robertson	Paddy	Jasmyn	Pietersen	T	9.5mm			FS + Mod13	**			**
Robertson	Paddy	Pietersen	Richter	T	13.2+6.7		****	DE ??	**	***		**
Robertson	Paddy	Richter	Paul Kruger	T	9.5mm			DE ??		***		**
Robertson	Parel	Dordrecht	Unnamed Road 1001	t	6.7mm			DE ??		*****		**
Robertson	Park	Eerste	Hager	t	6.7mm			DE ??	**	*		**
Robertson	Parking	Solomon	Cul De Sac	t	13.2+6.7			DE ??		***		
Robertson	Paul Kruger	Voortrekker	Konstitusie	S	C Slurry		****	Rehab (M)		***		**
Robertson	Paul Kruger	Konstitusie	Victoria	S	C Slurry		****	Rehab (M)	**			**
Robertson	Paul Kruger	Victoria	Adderley	S	C Slurry			Mod 13.2		*		***
Robertson	Paul Kruger	Adderley	Hoop	S	C Slurry			Mod 13.2				**
Robertson	Paul Kruger	Hoop	Swellendam	S	C Slurry			Asphalt (AC)		**		
Robertson	Paul Kruger	Robertson	Van Reenen	S	9.5mm							**
Robertson	Paul Kruger	Van Reenen	White	S	C Slurry	REHAB	????	Rehab (H)	***			**
Robertson	Paul Kruger	White	Truter	S	C Slurry			Rehab (M)				**
Robertson	Paul Kruger	Truter	Albert	S	13.2+6.7		***	Rehab (M)				**
Robertson	Paul Kruger	Albert	Le Roux	S	13.2+6.7			Rehab (M)				**



PAVEMENT MANAGEMENT SYSTEM

PAVEMENT ASSESSMENT (PHASE 1)



Client: **Langeberg**

28/10/2015

Routine Maintenance

Langeberg

Assessment Date : 2011/05

Suburb	Street :	Segment From To	Route Class	Existing Surfacing	Attention Required			Patching Surfacing	Edge Struc	Crack Break	Seal
Robertson	Paul Kruger	Le Roux	Van Zyl	S	13.2+6.7		Rehab (HS)	**	*		**
Robertson	Paul Kruger	Van Zyl	Loop	S	F Slurry						
Robertson	Paul Kruger	Loop	Polack	S	13.2+6.7						*
Robertson	Paul Kruger	Waterkant	Coetzee	S	13.2+6.7	***	Rehab (HS)	**	*		**
Robertson	Paul Kruger	Coetzee	Paddy	S	13.2+6.7	***	DE ??				**
Robertson	Paul Kruger	Paddy	Tar/Gravel	S	13.2+6.7	***	Rehab (L)	**	***	***	
Robertson	Paul Kruger	Gravel/Tar	Prov Road	S	13.2+6.7	****	Rehab (L)	***	***	***	
Robertson	Petunia	Begonia	Roos	t	F Slurry		9.5mm	**			**
Robertson	Piet Retief	Polack	Loop	t	C Slurry		Slurry (CS)		**		**
Robertson	Piet Retief	Loop	Van Zyl	t	C Slurry		Mod 9.5				**
Robertson	Piet Retief	Van Zyl	Le Roux	t	C Slurry		9.5mm		*		**
Robertson	Piet Retief	Albert	Truter	t	C Slurry		9.5mm				**
Robertson	Piet Retief	White	Van Reenen	t	F Slurry	****	Rehab (HS)	**			**
Robertson	Piet Retief	Van Reenen	Robertson	t	F Slurry		Mod 9.5				**
Robertson	Piet Retief	Swellendam	Hoop	T	F Slurry		Rehab (L)				**
Robertson	Piet Retief	Hoop	Adderley	T	F Slurry	****	Rehab (L)		***		**
Robertson	Piet Retief	Adderley	Victoria	T	F Slurry		Rehab (HS)				**
Robertson	Pietersen	Paddy	Africa	t	13.2+6.7		DE ??	**	*		**
Robertson	Pietersen	Meyer	Meyer	t	13.2+6.7	****	Rehab (L)	***	*****		
Robertson	Pietersen	Meyer	Jansen	t	13.2+6.7		FS + Mod9				**
Robertson	Pietersen	Jansen	Paddy	t	13.2+6.7		DE ??	**	***		**
Robertson	Plein	Watsonia	Nutan	t	9.5mm	REHAB	????	Rehab (L)	*****	*****	



PAVEMENT MANAGEMENT SYSTEM

PAVEMENT ASSESSMENT (PHASE 1)



Client: **Langeberg**

28/10/2015

Routine Maintenance

Langeberg

Assessment Date : 2011/05

Suburb	Street :	Segment		Route Class	Existing Surfacing	Attention Required			Patching		Edge Break	Crack Seal
		From	To			Rehab	Reseal	Action	Surfacing	Struc		
Robertson	Polack	Ash	Smith	t	C Slurry		***	Rehab (L)	*	***		**
Robertson	Polack	Smith	Van Oudtshoorn	t	C Slurry			Rehab (M)				**
Robertson	Polack	Van Oudtshoorn	Gum Grove	t	C Slurry			9.5mm				**
Robertson	Polack	Gum Grove	Roodezandt	t	C Slurry			9.5mm		***		**
Robertson	Polisie	Kromhout	Cul De Sac	t	F Slurry		****	Mod 9.5	*	***		**
Robertson	Protea	Hospital	Vygie	t	6.7mm		****	Slurry (FS)	**	***		**
Robertson	Protea	Vygie	Heide	t	6.7mm		***	DE ??	***	***		**
Robertson	Reitz	Van Zyl	Le Roux	t	F Slurry			Mod 9.5				**
Robertson	Reitz	Warren	Truter	T	F Slurry		****	Rehab (L)	**			**
Robertson	Reitz	Truter	White	T	F Slurry		****	13.2mm				**
Robertson	Reitz	White	Van Reenen	t	C Slurry			Rehab (M)				**
Robertson	Reitz	Van Reenen	Kerk	t	9.5mm			DE ??	*			*
Robertson	Reitz	Victoria	Konstitusie	T	9.5mm			FS + Mod13				*
Robertson	Reitz	Konstitusie	Voortrekker	T	9.5mm			Slurry (FS)				*
Robertson	Richter	Paddy	Cul De Sac	t	13.2+6.7			Rehab (L)	***	*****		**
Robertson	Rijger	Van Zyl	Van Riebeeck	t	13.2+6.7			DE ??		***		**
Robertson	River	Hospital	Hokim	t	C Slurry			9.5mm	**	*		
Robertson	Robertson	Paul Kruger	Piet Retief	T	C Slurry		****	Rehab (M)	**			**
Robertson	Robertson	Piet Retief	Barry	T	F Slurry			Rehab (M)				**
Robertson	Roodezandt	Polack	Wavern									



PAVEMENT MANAGEMENT SYSTEM

PAVEMENT ASSESSMENT (PHASE 1)



Client: **Langeberg**

28/10/2015

Routine Maintenance

Langeberg

Assessment Date : 2011/05

Suburb	Street :	Segment		Route Class	Existing Surfacing	Attention Required			Patching		Edge	Crack
		From	To			Rehab	Reseal	Action	Surfacing	Struc	Break	Seal
Robertson	Scholtz	Eerste	Wesley	t	13.2+6.7		***	Slurry (FS)	**	**		**
Robertson	Smal	White	Malherbe	t	13.2+6.7			DE ??		**		
Robertson	Smith	Polack	Waterkant	t	C Slurry			Mod 9.5	*			**
Robertson	Sonneblom	Cul De Sac	Jasmyn	t	C Slurry			Mod 9.5		*****		**
Robertson	Sonneblom	Japonika	Begonia	t	C Slurry		****	9.5mm	***			**
Robertson	Sonneblom	Begonia	Watsonia	t	C Slurry		***	9.5mm	**	***		***
Robertson	Sonskyn	Tweede	Eerste	t	F Slurry			Mod 9.5				**
Robertson	Swellendam	Barry	Piet Retief	T	C Slurry		***	Rehab (M)	*			**
Robertson	Swellendam	Piet Retief	Paul Kruger	T	C Slurry		****	CS + Mod13				**
Robertson	Tindall	Polack	Coetzee	t	13.2+6.7		***	Slurry (FS)	***			**
Robertson	Toets Sentrum	Kerk	Kerk	t	13.2+6.7			Slurry (FS)	**	***		
Robertson	Truter	Piet Retief	Paul Kruger	t	C Slurry			Mod 9.5				**
Robertson	Truter	Paul Kruger	Reitz	t	C Slurry			9.5mm		***		**
Robertson	Truter	Reitz	Dirkie Uys	t	C Slurry			9.5mm				**
Robertson	Tulp	Japonika	Cul De Sac	t	F Slurry		****	Mod 9.5	*****	*****		
Robertson	Tweede	Vierde	Sonskyn	t	13.2+6.7			DE ??		**		
Robertson	Unnamed Road 0002	Langeberg	Malva	t	ASPH(C)			9.5mm	**	***		**
Robertson	Unnamed Road 0004	Iris	Jubel	t	13.2+6.7		****	Slurry (FS)	***	***		**
Robertson	Unnamed Road 0005	Iris	Heuwel	t	F Slurry		****	9.5mm	***	***		***
Robertson	Unnamed Road 000											



PAVEMENT MANAGEMENT SYSTEM

PAVEMENT ASSESSMENT (PHASE 1)



Client: **Langeberg**

28/10/2015

Routine Maintenance

Langeberg

Assessment Date : 2011/05

Suburb	Street :	Segment		Route Class	Existing Surfacing	Attention Required			Patching		Edge	Crack
		From	To			Rehab	Reseal	Action	Surfacing	Struc	Break	Seal
Robertson	Van Reenen	Paul Kruger	Reitz	T	C Slurry			Rehab (M)				**
Robertson	Van Reenen	Reitz	Cul De Sac	T	C Slurry		****	13.2mm	**	***		**
Robertson	Van Riebeeck	Cul De Sac	Rijger	t	13.2+6.7			Slurry (FS)	**	**		
Robertson	Van Zyl	Geelhout	Ficus	T	9.5mm			Rehab (M)				**
Robertson	Van Zyl	Ficus	Elm	T	9.5mm			Slurry (FS)	*			**
Robertson	Van Zyl	Rijger	Denne	T	9.5mm			DE ??		**		
Robertson	Van Zyl	Bloekom	Akker	T	6.7mm			Mod 13.2				**
Robertson	Van Zyl	Akker	Dirkie Uys	T	6.7mm			13.2mm	**	***		**
Robertson	Van Zyl	Dirkie Uys	King	T	6.7mm		****	13.2mm	***			**
Robertson	Van Zyl	King	Neethling	T	6.7mm			Mod 13.2		***		**
Robertson	Van Zyl	Neethling	Van Oudtshoorn	T	C Slurry			Mod 13.2				**
Robertson	Van Zyl	Van Oudtshoorn	Reitz	T	9.5mm			DE ??		**		
Robertson	Van Zyl	Paul Kruger	Piet Retief	T	C Slurry			13.2mm				**
Robertson	Van Zyl	Piet Retief	Barry	T	C Slurry			13.2mm				**
Robertson	Van Zyl	Barry	Keerom	t	6.7mm			Mod 9.5				**
Robertson	Van Zyl	Keerom	Hopley	t	C Slurry			9.5mm				**
Robertson	Van Zyl	Hopley	Alberta	t	C Slurry			9.5mm		***		
Robertson	Van der Stel	Malherbe	Constantia	t	6.7mm			9.5mm		***		**
Robertson	Victoria	CDS North	Barry	t	6.7mm			FS + Mod9	*	*****		**
Robertson	Victoria	Barry										



PAVEMENT MANAGEMENT SYSTEM

PAVEMENT ASSESSMENT (PHASE 1)



Client: **Langeberg**

28/10/2015

Routine Maintenance

Langeberg

Assessment Date : 2011/05

Suburb	Street :	Segment		Route Class	Existing Surfacing	Attention Required			Patching		Edge	Crack
		From	To			Rehab	Reseal	Action	Surfacing	Struc	Break	Seal
Robertson	Waterkant	Smith	Bosheuwel	t	C Slurry			CS + Mod9				**
Robertson	Waterkant	Bosheuwel	Ash	t	C Slurry			9.5mm				**
Robertson	Waterkant	Ash	Dordrecht	T	C Slurry		***	13.2mm	**	***		**
Robertson	Waterkant	Dordrecht	Paul Kruger	t	C Slurry			Mod 9.5		***		**
Robertson	Watsonia	Nerina	Petunia	t	C Slurry		****	9.5mm	***	***		**
Robertson	Watsonia	Petunia	Rosita	t	9.5mm			9.5mm				**
Robertson	Watsonia	Rosita	Sonneblom	t	C Slurry			9.5mm				**
Robertson	Watsonia	Sonneblom	Plein	t	C Slurry			9.5mm	**	***		**
Robertson	Watsonia	Plein	Nutan	t	C Slurry			9.5mm	**			
Robertson	Watsonia	Nutan	Japonika	t	C Slurry		****	9.5mm	**	***		**
Robertson	Watsonia	Japonika	Jasmyn	t	C Slurry		****	9.5mm	***			**
Robertson	Wavern	Roodezandt	Gum Grove	t	6.7mm			Slurry (FS)	*			**
Robertson	Wavern	Gum Grove	Van Oudtshoorn	t	6.7mm			Slurry (CS)				**
Robertson	Wesley	Paddy	Wesley Link	T	13.2+6.7		***	DE ??	**	**		
Robertson	Wesley	Wesley Link	Hospital	T	F Slurry			Mod 13.2				**
Robertson	Wesley	Hospital	Coetzee	T	F Slurry		****	Rehab (H)	**			**
Robertson	Wesley	Coetzee	Scholtz	T	9.5mm				**	*		**
Robertson	Wesley CDS	CDS North	Wesley Link	t	C Slurry			9.5mm				**
Robertson	Wesley CDS	Wesley Link	CDS South	t	C Slurry			9.5mm				**
Robertson	White	Cul De										



PAVEMENT MANAGEMENT SYSTEM

PAVEMENT ASSESSMENT (PHASE 1)



Client: Langeberg

28/10/2015

Routine Maintenance

Langeberg

Assessment Date : 2011/05

Suburb	Street :	Segment		Route Class	Existing Surfacing	Attention Required			Patching		Edge Break	Crack Seal
		From	To			Rehab	Reseal	Action	Surfacing	Struc		
Zolani	Booyesen	Ndinisa	Cul De Sac	t	9.5mm			DE ??	**	***		
Zolani	Bougard	Klaas	Khosi	t	9.5mm			DE ??		***		
Zolani	Bougard	Khosi	Dudumashe	t	9.5mm			DE ??	**	**		
Zolani	Building	Majola	Klaas	T	9.5mm			DE ??				**
Zolani	Building	Klaas	Tyhalisisu	T	9.5mm			DE ??				**
Zolani	Building	Maqolo	N32	T	9.5mm		****	DE ??	***	**		**
Zolani	Dudumashe	Ndinisa	Tshoto	t	9.5mm			DE ??	*			
Zolani	Gaveni	Tshoto	Cul De Sac	t	9.5mm			DE ??		***		
Zolani	Gwebityala	Matroos	Mase	t	9.5mm			DE ??	*	**		**
Zolani	Khosi	Maqolo	Quwe/Jantjies	t	9.5mm			Slurry (FS)	**	*		
Zolani	Khosi	Tyhalisisu	Bougard	t	9.5mm			DE ??		***		
Zolani	Khuselo	Gravel/Tar	Dudumashe	t	F Slurry					**		
Zolani	Mafuya	Zwedala	Dudumashe	t	9.5mm		***	Slurry (FS)	***	*****		
Zolani	Mantlana	Suluba	Mbeka	t	ASPH(C)			9.5mm	**			***
Zolani	Maqolo	Cul De Sac	Building	t	13.2+6.7		***	DE ??	***	*****		**
Zolani	Maqolo	Gcwabe	Jantjies	t	9.5mm			DE ??		*****		
Zolani	Maqolo	Jantjies	Khosi	t	6.7mm			DE ??	**	**		*****
Zolani	Matroos	Mase	Ndinisa	t	9.5mm			DE ??	**	*		
Zolani	Matroos	Ndinisa	Gwebityala	t	9.5mm			DE ??		*****		
Zolani	Matroos	Gwebityala</										



PAVEMENT MANAGEMENT SYSTEM

PAVEMENT ASSESSMENT (PHASE 1)



Client: Langeberg

28/10/2015

Routine Maintenance

Langeberg

Assessment Date : 2011/05

Suburb	Street :	Segment		Route Class	Existing Surfacing	Attention Required			Patching		Edge	Crack
		From	To			Rehab	Reseal	Action	Surfacing	Struc	Break	Seal
Zolani	Ntantisio	Ndinisa	Cul De Sac	t	9.5mm			DE ??	*****			
Zolani	Road 1	Road 5	Road 6	t	F Slurry				*****			
Zolani	Road 1	Road 6	Road 3	t	F Slurry				*****			
Zolani	Spofana	Khosi	Quwe	t	9.5mm			DE ??				**
Zolani	Spofana	Quwe	Khuse	t	9.5mm			DE ??	*			
Zolani	Tshoto	Nogemane	Gaveni	t	9.5mm		****	Slurry (FS)	***	***		
Zolani	Tyhalisisu	Faleni	Khosi	t	9.5mm			Mill+Replace	***	*	***	